Date 7/3/26 — R1005 — 2 — Facing Andoom — Shift Driver/s PETE-JED — Day / (Night) Shift

The following checks are to be performed at shift handover or close as practical

Vigilance Operational	Engine Oil	Radiator Water	End of Rake Marker Operational	Rake Leakage Check kPa
(Yes) No	(Ok) Not OK Topped up	(OK) Not Ok Topped Up	Rake 1 (Y) N Rake 2 (Y) N Rake 3 (Y) N	Rake 1 Rake 2 0 Rake 3 0
Loco Comp Oil: (OK) Not OK Topped Up				

Record time comp car/loco hrs taken

			Lead	Rake1	2nd	Lead	Rake2	2nd	Lead	Rake3	2nd	Locomotive
Rake 1		Engine Oil	Comp Car Amt Added	Comp Car Amt Added		Comp Car Amt Added	Comp Car Amt Added		Comp Car Amt Added	Comp Car Amt Added		Radiator Water added(mm s/glass)
Rake 2		Comp Oil	Amt Added	Amt Added		Amt Added	Amt Added		Amt Added	Amt Added		Amt Added
Rake 3		Comp Hrs										Amt Added
		Next Service										Loco Hrs 23256
Locomotive	17:19		Running in Auto / Manual Not Running	Running in Auto / Manual Not Running		Running in Auto / Manual Not Running	Running in Auto / Manual Not Running		Running in Auto / Manual Not Running	Running in Auto / Manual Not Running		Cab Cleaned COVID
Fuel added to comp cars / Loco			Ltr's	Ltr's		Ltr's	Ltr's		Ltr's	Ltr's		Loco Km's Travelled 474530
												1200 Ltrs

Trip No	Dump Station Arrival Time	Dump Station Green Light	Load Station Arrival Time	Load Station Green Light	Delay to Production Yes / No	Delay Time minutes	Rake No	Reason for Delay	Manual Brake Pipe Continuity Completed (Train Drivers Initials Required)
1	1447		1600	1605	N		3		
2	1640		1716	1747	N		1		
3	1822		1857	1935	N		2		
4	2010		2045	2119	No		3	m/c	PA
5	2156		2226	2318	No		1	m/c	PA
6	2353		0024	0122	No		2		
7	0157		0235	0308	No		3		
8	0343							Refuel Loco 1200L	
9									
10									
11									
12									

Time of Fault/Delay	Fault/Delay Description	Notification Raised	Notification No.

A Continuity Test must be done before moving the Train after Rake changeover!

Document reviewed and necessary Notifications/Maintenance Orders raised. Crewleader Signature.....