Date 12/01/26 Loco No. R1005 Cab No 2 Facing Andoom Shift Driver/s GARY Day (Night) Shift

The following checks are to be performed at shift handover or close as practical

Vigilance Operational	Engine Oil	Radiator Water	End of Rake Marker Operational	Rake Leakage Check kPa
(Yes) No	(Ok) Not OK Topped up	(OK) Not Ok Topped Up	Rake 1 (Y) N Rake 2 (Y) N Rake 3 (Y) N	Rake 1 0 Rake 2 0 Rake 3 0
Loco Comp Oil	(OK) Not OK Topped Up			

Record time comp car/loco hrs taken			Lead Rake1 2nd	Lead Rake2 2nd	Lead Rake3 2nd	Locomotive
Rake 1		Engine Oil	Comp Car / Amt Added	Comp Car / Amt Added	Comp Car / Amt Added	Radiator Water added(mm s/glass)
Rake 2		Comp Oil	Comp Car / Amt Added	Comp Car / Amt Added	Comp Car / Amt Added	Amt Added
Rake 3		Comp Hrs	Amt Added	Amt Added	Amt Added	Amt Added
		Next Service				Loco Hrs 22141
Locomotive	1700		Running in Auto / Manual Not Running	Running in Auto / Manual Not Running	Running in Auto / Manual Not Running	Cab Cleaned COVID
Fuel added to comp cars / Loco			Ltr's	Ltr's	Ltr's	Loco Km's Travelled 453707
						2500 Ltrs

Trip No	Dump Station Arrival Time	Dump Station Green Light	Load Station Arrival Time	Load Station Green Light	Delay to Production Yes / No	Delay Time minutes	Rake No	Reason for Delay	Manual Brake Pipe Continuity Completed (Train Drivers Initials Required)
1	~~1528~~		1528	1703	NO		1		GH TL
2	1736		1812	1834	NO		2		GH DT
3	1907		1938	2013	NO		3		GH SB
4	2046		2145	2204				Meal Break	
5	2237		2310	2355	NO				
6	0028		0111	0154	NO				
7	0227		0320	0350	NO			Fuel loco	
8	0423								
9									
10									
11									
12									

Time of Fault/Delay	Fault/Delay Description	Notification Raised	Notification No.

A Continuity Test must be done before moving the Train after Rake changeover!

Document reviewed and necessary Notifications/Maintenance Orders raised. Crewleader Signature.....