Date 21/06/2026 Loco No. RL005 Cab No 2 Facing Andoom Shift Driver/s NEVILLE // ADAM (Day) Night Shift

The following checks are to be performed at shift handover or close as practical

Vigilance Operational	Engine Oil ↓150	Radiator Water ↓ 25mm	End of Rake Marker Operational	Rake Leakage Check kPa
(Yes) No	Ok (Not OK) Topped up	(OK) Not Ok Topped Up	Rake 1 (Y) N Rake 2 (Y) N Rake 3 (Y) N	Rake 1 2 Rake 2 0 Rake 3
Loco Comp Oil	(OK) Not OK Topped Up			

Record time comp car/loco hrs taken			Lead	Rake1	2nd	Lead	Rake2	2nd	Lead	Rake3	2nd	Locomotive
			Comp Car J	Comp Car O		Comp Car P	Comp Car K		Comp Car N	Comp Car I		Radiator Water added(mm s/glass)
Rake 1	0345	Engine Oil	Amt Added	Amt Added		Amt Added	Amt Added		Amt Added	Amt Added		Amt Added
Rake 2	0530	Comp Oil	Amt Added	Amt Added		Amt Added	Amt Added		Amt Added	Amt Added		Amt Added
Rake 3	0700	Comp Hrs	16423	33200		16615	8188		35755	11137		Loco Hrs 25045
		Next Service	16500	33500		17057	9100		36052	11000		Cab Cleaned COVID
Locomotive	0430		Running in Auto / Manual (Not Running)	Running in Auto / Manual (Not Running)		(Running in Auto) Manual Not Running	Running in Auto / Manual (Not Running)		Running in Auto / Manual (Not Running)	Running in Auto / Manual (Not Running)		Loco Km's Travelled 504942
Fuel added to comp cars / Loco			Ltr's	Ltr's		Ltr's	Ltr's		Ltr's	Ltr's		2100, Ltrs

Trip No	Dump Station Arrival Time	Dump Station Green Light	Load Station Arrival Time	Load Station Green Light	Delay to Production Yes / No	Delay Time minutes	Rake No	Reason for Delay	Manual Brake Pipe Continuity Completed (Train Drivers Initials Required)
1	0410		0444	0502	N		1	MC	M.M.
2	0537		0615	0634	N		2		
3	0710		0825	0827	Y	18F, 32P	3	Shunt Comp I out Comp "M" in	
4	0903		0950	1000	N		1	Swap Loco's 7 in production	
5	1036		1121	1136	N		2	2100 Fuel Loco 5	
6	1211		1245	1300	N		3		
7	1335		1410	1425	N		1		
8	1500		1538	1555			2		
9	1630						3		
10									
11									
12									

Time of Fault/Delay	Fault/Delay Description	Notification Raised	Notification No.
	R3 shunt compI out CompM in		
0830	R3 Comp M in Manual Load		
1425	R3 Comp M " "		

A Continuity Test must be done before moving the Train after Rake changeover!

Document reviewed and necessary Notifications/Maintenance Orders raised. Crewleader Signature.....

Date 21/6/26 Loco No. R1007 Cab No 2 Facing Andoom Shift Driver/s MOLLY-TRUDI Day (Night) Shift

The following checks are to be performed at shift handover or close as practical

Vigilance Operational	Engine Oil	Radiator Water	End of Rake Marker Operational	Rake Leakage Check kPa
(Yes) No	(Ok) Not OK Topped up	(OK) Not Ok Topped Up	Rake 1 Y N Rake 2 Y N Rake 3 Y N	Rake 1 Rake 2 Rake 3
Loco Comp Oil	(OK) Not OK Topped Up			

Record time comp car/loco hrs taken			Lead	Rake1	2nd	Lead	Rake2	2nd	Lead	Rake3	2nd	Locomotive
Rake 1		Engine Oil	Comp Car Amt Added	Comp Car Amt Added		Comp Car Amt Added	Comp Car Amt Added		Comp Car Amt Added	Comp Car Amt Added		Radiator Water added(mm s/glass)
Rake 2		Comp Oil	Amt Added	Amt Added		Amt Added	Amt Added		Amt Added	Amt Added		Amt Added
Rake 3		Comp Hrs										Loco Hrs
		Next Service										Cab Cleaned COVID
Locomotive			Running in Auto / Manual Not Running	Running in Auto / Manual Not Running		Running in Auto / Manual Not Running	Running in Auto / Manual Not Running		Running in Auto / Manual Not Running	Running in Auto / Manual Not Running		Loco Km's Travelled
Fuel added to comp cars / Loco			Ltr's	Ltr's		Ltr's	Ltr's		Ltr's	Ltr's		1700 Ltrs

Trip No	Dump Station Arrival Time	Dump Station Green Light	Load Station Arrival Time	Load Station Green Light	Delay to Production Yes / No	Delay Time minutes	Rake No	Reason for Delay	Manual Brake Pipe Continuity Completed (Train Drivers Initials Required)
1	1630		1741	1720	NO		3	MC	~~MM.~~ MM.
2	1755		1830	1845	~~NO~~		1	MC	MM.
3	1925		2018	2029	YES		2	rake had not finished dumping MC	MM.
4	2110		2146	2205	NO		3		
5	2240		2316	2334	NO		1		
6	0008		0038	0057	NO		2	1720L fuel	
7	0131		0200	0222	NO		3		
8	0256		0325	0357	NO		1		
9	0431						2		
10									
11									
12									

Time of Fault/Delay	Fault/Delay Description	Notification Raised	Notification No.

A Continuity Test must be done before moving the Train after Rake changeover!

Document reviewed and necessary Notifications/Maintenance Orders raised. Crewleader Signature.....