Date 21/9/26 Loco No. R1007 Cab No 2 Facing Andoom Shift Driver/s TRUDI (Day) Night Shift

The following checks are to be performed at shift handover or close as practical

| Vigilance Operational | Engine Oil | Radiator Water | End of Rake Marker Operational | Rake Leakage Check kPa |
|---|---|---|---|---|
| Yes / No | (Ok) / Not OK / Topped up | (Ok) / Not Ok / Topped Up | Rake 1 (Y) N Rake 2 (Y) N Rake 3 (Y) N | Rake 1 0 Rake 2 0 Rake 3 0 |

| Loco Comp Oil ? | OK / Not OK / Topped Up | Lead | Rake1 | 2nd | Lead | Rake2 | 2nd | Lead | Rake3 | 2nd | Locomotive |
|---|---|---|---|---|---|---|---|---|---|---|---|
| Record time comp car/loco hrs taken | | Comp Car P | Comp Car J | | Comp Car O | Comp Car K | | Comp Car I | Comp Car M | | Radiator Water added(mm s/glass) |
| Rake 1 | 0549 | Engine Oil Amt Added | Amt Added | | Amt Added | Amt Added | | Amt Added | Amt Added | | Amt Added |
| Rake 2 | 1210 | Comp Oil Amt Added | Amt Added | | Amt Added | Amt Added | | Amt Added | Amt Added | | Amt Added |
| Rake 3 | 0417 | Comp Hrs | 174424 | 17135 | 33922 | 8682 | | 11635 | 18912 | | Loco Hrs |
| | | Next Service | 18137 | 17500 | 34508 | 9100 | | 12000 | 19000 | | Cab Cleaned (COVID) |
| Locomotive | 0626 | Running in Auto / Manual / Not Running | Running in Auto / Manual (Not Running) | | Running in Auto / Manual / Not Running | Running in Auto / Manual (Not Running) | | Running in Auto / Manual (Not Running) | Running in Auto / Manual (Not Running) | | Loco Km's Travelled |
| Fuel add Rake comp cars // Loco | | Ltr's | Ltr's | | Ltr's | Ltr's | | Ltr's | Ltr's | | 535-84-C4 Ltrs |

| Trip No | Dump Station Arrival Time | Dump Station Green Light | Load Station Arrival Time | Load Station Green Light | Delay to Production Yes / No | Delay Time minutes | Rake No | Reason for Delay | Manual Brake Pipe Continuity Completed (Train Drivers Initials Required) |
|---|---|---|---|---|---|---|---|---|---|
| 1 | 0422 | ✓ | 0505 | 0510 | NO | | 3 | | T + Pete |
| 2 | 0544 | | 0623 | 0631 | NO | | 1 | | R + Pete |
| 3 | 0705 | | 0740 | 0754 | NO | | 2 | | R + DT |
| 4 | 0828 | | 0900 | 0919 | NO | | 3 | | |
| 5 | 0953 | | 1108 | 1129 | NO | | 1 | Crew Break 1010 – 1040 | |
| 6 | 1203 | | 1245 | 1258 | NO | | 2 | | |
| 7 | 1332 | | 1408 | 1426 | NO | | 3 | | |
| 8 | 1502 | | | | | | 1 | | |
| 9 | | | | | | | | | |
| 10 | | | | | | | | | |
| 11 | | | | | | | | | |
| 12 | | | | | | | | | |

| Time of Fault/Delay | Fault/Delay Description | Notification Raised | Notification No. |
|---|---|---|---|
| | R1 rolled by - 2nd last (cc) making noise (track team) | | |
| | (W) boards MRB - removed 1315 | | |
| | | | |

**A Continuity Test must be done before moving the Train after Rake changeover!**

*Document reviewed and necessary Notifications/Maintenance Orders raised. Crewleader Signature.....*