Date 24/8/26 Loco No. R1005 Cab No 2 Facing Andoom Shift Driver/s Trudi Gary (Day) Night Shift

**The following checks are to be performed at shift handover or close as practical**

| Vigilance Operational | Engine Oil | Radiator Water | End of Rake Marker Operational | Rake Leakage Check kPa |
|---|---|---|---|---|
| (Yes) No | (Ok) Not OK Topped up | (OK) Not Ok Topped Up | Rake 1 (Y) N Rake 2 (Y) N Rake 3 (Y) N | Rake 1 Rake 2 Rake 3 |
| Loco Comp Oil | (OK) Not OK Topped Up | | | |

| | Lead | Rake1 | 2nd | Lead | Rake2 | 2nd | Lead | Rake3 | 2nd | Locomotive |
|---|---|---|---|---|---|---|---|---|---|---|
| Record time comp car/loco hrs taken | Comp Car P | Comp Car N | | Comp Car O | Comp Car K | | Comp Car J | Comp Car M | | Radiator Water added(mm s/glass) |
| Rake 1 0540 — Engine Oil | Amt Added | Amt Added | | Amt Added | Amt Added | | Amt Added | Amt Added | | Amt Added |
| Rake 2 0720 — Comp Oil | Amt Added | Amt Added | | Amt Added | Amt Added | | Amt Added | Amt Added | | Amt Added |
| Rake 3 0410 — Comp Hrs | 17258 | 36175 | | 33612 | 8522 | | 16868 | 14704 | | Loco Hrs 25796 |
| Next Service | 18157 | 36800 | | 34500 | 9100 | | 17500 | 19000 | | Cab Cleaned COVID |
| Locomotive 0415 | Running in Auto / Manual (Not Running) | Running in Auto / Manual Not Running | | Running in Auto / Manual (Not Running) | Running in Auto / Manual Not Running | | Running in Auto / Manual (Not Running) | Running in Auto / Manual Not Running | | Loco Km's Travelled 522706 |
| Fuel added to comp cars / Loco | Ltr's | Ltr's | | Ltr's | Ltr's | | Ltr's | Ltr's | | 1800(S) Ltrs |

| Trip No | Dump Station Arrival Time | Dump Station Green Light | Load Station Arrival Time | Load Station Green Light | Delay to Production Yes / No | Delay Time minutes | Rake No | Reason for Delay | Manual Brake Pipe Continuity Completed (Train Drivers Initials Required) |
|---|---|---|---|---|---|---|---|---|---|
| 1 | 0410 | | 0442 | 0508 | NO | | 3 | | |
| 2 | 0541 | | 0614 | 0647 | NO | | 1 | | GH a |
| 3 | 0720 | | 0750 | 0816 | NO | | 2 | | GH a |
| 4 | 0849 | | 0919 | 1000 | NO | | 3 | | GH a |
| 5 | 1033 | | | 1158 | Y | | 1 | Shunt: 2107 out / 2054 in | TR + WSLop DT |
| 6 | 1232 | | 1302 | 1351 | NO | | 2 | R1 CC N out / CC I in | |
| 7 | 1425 | | 1456 | 1532 | NO | | 3 | Blue back into service | |
| 8 | 1606 | | | | | | | | |
| 9 | | | | | | | | | |
| 10 | | | | | | | | | |
| 11 | | | | | | | | | |
| 12 | | | | | | | | | |

| Time of Fault/Delay | Fault/Delay Description | Notification Raised | Notification No. |
|---|---|---|---|
| | 1800L Loco 5 | | |
| | | | |
| | | | |

**A Continuity Test must be done before moving the Train after Rake changeover!**

*Document reviewed and necessary Notifications/Maintenance Orders raised. Crewleader Signature.....*