Date 24/05/26 Loco No. 1005 Cab No 2 Facing Andoom Shift Driver/s ADAM – NEV Day (Night) Shift

The following checks are to be performed at shift handover or close as practical

Vigilance Operational	Engine Oil	Radiator Water	End of Rake Marker Operational	Rake Leakage Check kPa
(Yes) No	(Ok) Not OK Topped up	(OK) Not Ok Topped Up	Rake 1 (Y) N Rake 2 (Y) N Rake 3 (Y) N	Rake 1 ( ) Rake 2 ( ) Rake 3 ( )

Loco Comp Oil ? (OK) Not OK Topped Up

Record time comp car/loco hrs taken			Lead	Rake1	2nd	Lead	Rake2	2nd	Lead	Rake3	2nd	Locomotive
Rake 1		Engine Oil	Comp Car Amt Added	Comp Car Amt Added		Comp Car Amt Added	Comp Car Amt Added		Comp Car Amt Added	Comp Car Amt Added		Radiator Water added(min e/gless) Amt Added
Rake 2		Comp Oil	Amt Added	Amt Added		Amt Added	Amt Added		Amt Added	Amt Added		Amt Added
Rake 3		Comp Hrs										Loco Hrs
		Next Service										Cab Cleaned covid
Locomotive	1646		Running In Auto / Manual Not Running	Running In Auto / Manual Not Running		Running In Auto / Manual Not Running	Running In Auto / Manual Not Running		Running In Auto / Manual Not Running	Running In Auto / Manual Not Running		Loco Km's Travelled 5231969
Fuel added to comp cars/ loco			Ltr's	Ltr's		Ltr's	Ltr's		Ltr's	Ltr's		2400 Ltrs

Trip No	Dump Station Arrival Time	Dump Station Green Light	Load Station Arrival Time	Load Station Green Light	Delay to Production Yes / No	Delay Time minutes	Rake No	Reason for Delay	Manual Brake Pipe Continuity Completed (Train Drivers Initials Required)
1	1606		1645	1708	N		1		
2	1743		1824	1835	N		2		
3	1910		1947	2001	N		3		
4	2036		2100	2131	N		1		
5	2206		2244	2254	N		2		
6	2330		0003	0018	N		3		
7	0053		0128	0155	N		1	OP fuel dropped air @ ANDOOM	
8	0230		0322	0347	N		2	fuel loco	
9	0423						3		
10									
11									
12									

Time of Fault/Delay	Fault/Delay Description	Notification Raised	Notification No.

A Continuity Test must be done before moving the Train after Rake changeover!

Document reviewed and necessary Notifications/Maintenance Orders raised. Crewleader Signature.....