Date 26/4/26 Loco No. 2005 Cab No 1 Facing Andoom Shift Driver/s NEW / ADAM (Day) Night Shift

The following checks are to be performed at shift handover or close as practical

| Vigilance Operational | Engine Oil | Radiator Water | End of Rake Marker Operational | Rake Leakage Check kPa |
|---|---|---|---|---|
| (Yes) No | (OK) Not OK Topped up √ 100 | (OK) Not Ok Topped Up | Rake 1 (Y) N Rake 2 (Y) N Rake 3 (Y) N | Rake 1 (OK) Rake 2 Rake 3 |
| Loco Comp Oil | (OK) Not OK Topped Up | | | |

Record time comp car/loco hrs taken

| | |
|---|---|
| Rake 1 | 0425 |
| Rake 2 | |
| Rake 3 | |
| Locomotive | 0400 |

Fuel added to comp cars / loco

| | Lead Rake1 | 2nd | Lead Rake2 | 2nd | Lead Rake3 | 2nd | Locomotive |
|---|---|---|---|---|---|---|---|
| | Comp Car J | Comp Car K | Comp Car P | Comp Car N | Comp Car I | Comp Car M | Radiator Water added(mm s/glass) |
| Engine Oil | Amt Added | Amt Added | Amt Added | Amt Added | Amt Added | Amt Added | Amt Added |
| Comp Oil | Amt Added | Amt Added | Amt Added | Amt Added | Amt Added | Amt Added | Amt Added |
| Comp Hrs | 15936 | 7434 | 16153 | 35532 | 10720 | 17898 | Loco Hrs 24111 |
| Next Service | 16500 | 8100 | 17057 | 36052 | 11000 | 18137 | Cab Cleaned COVID |
| | (Running In Auto / Manual Not Running) | Running In Auto / Manual (Not Running) | Running In Auto / Manual (Not Running) | Running In Auto / Manual (Not Running) | (Running In Auto / Manual Not Running) | Running In Auto / Manual (Not Running) | Loco Km's Travelled 487088 |
| | Ltr's | Ltr's | Ltr's | Ltr's | Ltr's | Ltr's | 866 Ltrs |

| Trip No | Dump Station Arrival Time | Dump Station Green Light | Load Station Arrival Time | Load Station Green Light | Delay to Production Yes / No | Delay Time minutes | Rake No | Reason for Delay | Manual Brake Pipe Continuity Completed (Train Drivers Initials Required) |
|---|---|---|---|---|---|---|---|---|---|
| 1 | 0246 | 0354 | 0419 | 0439 | N | | 1 | | |
| 2 | 0514 | | 0549 | 0658 | N | | 2 | ML | M.M |
| 3 | 0730 | | 0810 | 0913 | N | | 3 | ML | M.M |
| 4 | 0950 | | 1206 | 1206 | Y | | 1 | Compressor ISSUES K | |
| 5 | 1251 | | 1317 | 1419 | | | 2 | | |
| 6 | 1454 | | | | | | 3 | | |
| 7 | | | | | | | | | |
| 8 | | | | | | | | | |
| 9 | | | | | | | | | |
| 10 | | | | | | | | | |
| 11 | | | | | | | | | |
| 12 | | | | | | | | | |

866L fuel

| Time of Fault/Delay | Fault/Delay Description | Notification Raised | Notification No. |
|---|---|---|---|
| 10-1130 | Comp cark got issues | | |
| | | | |
| | | | |

**A Continuity Test must be done before moving the Train after Rake changeover!**

*Document reviewed and necessary Notifications/Maintenance Orders raised. Crewleader Signature.....*