Date 4/4/26 Loco No. R1007 Cab No 1 Facing Andoom Shift Driver/s TRUDI / ADAM (Day) Night Shift

The following checks are to be performed at shift handover or close as practical

Vigilance Operational	Engine Oil	Radiator Water		End of Rake Marker Operational	Rake Leakage Check kPa
(Yes) No	(Ok) Not OK Topped up	(OK) Not Ok Topped Up		Rake 1 (Y) N Rake 2 (Y) N Rake 3 (Y) N	Rake 1 0 Rake 2 0 Rake 3 0
Loco Comp Oil ?	OK Not OK Topped Up				

	Lead	Rake1	2nd	Lead	Rake2	2nd	Lead	Rake3	2nd	Locomotive
Record time comp car/loco hrs taken	Comp Car J	Comp Car L		Comp Car O	Comp Car N		Comp Car I	Comp Car M		Radiator Water added(mm s/glass)
Rake 1 0619	Engine Oil Amt Added	Amt Added		Amt Added	Amt Added		Amt Added	Amt Added		Amt Added
Rake 2 0836	Comp Oil Amt Added	Amt Added		Amt Added	Amt Added		Amt Added	Amt Added		Amt Added
Rake 3 0412	Comp Hrs 15774	7741		32847	35308		10554	17710		Loco Hrs
	Next Service 16500	8100		33500	?		11000	18137		Cab Cleaned COVID
Locomotive 0600	Running in Auto / Manual (Not Running)	Running in Auto / Manual Not Running		Running in Auto / Manual Not Running	Running in Auto / Manual (Not Running)		Running in Auto / Manual (Not Running)	Running in Auto / Manual Not Running		Loco Km's Travelled 492 901.5
Fuel added to comp cars / Loco	Ltr's	Ltr's		Ltr's	Ltr's		Ltr's	Ltr's		Ltrs

Trip No	Dump Station Arrival Time	Dump Station Green Light	Load Station Arrival Time	Load Station Green Light	Delay to Production Yes / No	Delay Time minutes	Rake No	Reason for Delay	Manual Brake Pipe Continuity Completed (Train Drivers Initials Required)
1	0415		0453	0600	N		3	m/c	
2	0634		0710	0802	N		1		
3	0836		0917	1017	N		2		
4	1051		1125	1228	N		3		
5	1303		1340	1440	N		1		
6	1515						2		
7							3		
8									
9									
10									
11									
12									

Time of Fault/Delay	Fault/Delay Description	Notification Raised	Notification No.

A Continuity Test must be done before moving the Train after Rake changeover!

Document reviewed and necessary Notifications/Maintenance Orders raised. Crewleader Signature.....