Date 05 / 01 / 2026 Loco No. R1005 Cab No 2 Facing Andoom Shift Driver/s NEV / GARY Day Night Shift

The following checks are to be performed at shift handover or close as practical

Vigilance Operational	Engine Oil ↓100	Radiator Water	End of Rake Marker Operational	Rake Leakage Check kPa
Yes No	OK Not OK Topped up	OK Not Ok Topped Up	Rake 1 Y N Rake 2 Y N Rake 3 Y N	Rake 1 0 Rake 2 Rake 3 0
Loco Comp Oil	OK Not OK Topped Up			

Record time comp car/loco hrs taken			Lead Rake1 2nd		Lead Rake2 2nd		Lead Rake3 2nd		Locomotive
			Comp Car N	Comp Car J	Comp Car F	Comp Car M	Comp Car K	Comp Car P	Radiator Water added(mm s/glass)
Rake 1	0350	Engine Oil	Amt Added	Amt Added	Amt Added	Amt Added	Amt Added	Amt Added	Amt Added
Rake 2	0740	Comp Oil	Amt Added	Amt Added	Amt Added	Amt Added	Amt Added	Amt Added	Amt Added
Rake 3	0430	Comp Hrs	34740	15352	9995	17086	6965	15197	Loco Hrs 21960
		Next Service	35000	15500	10000	17000	7001	16000	Cab Cleaned COVID
Locomotive	0400		Running in Auto / Manual Not Running	Running in Auto / Manual Not Running	Running in Auto / Manual Not Running	Running in Auto / Manual Not Running	Running in Auto / Manual Not Running	Running in Auto / Manual Not Running	Loco Km's Travelled 449092
Fuel added to comp cars / Loco			Ltr's	Ltr's	Ltr's	Ltr's	Ltr's	Ltr's	Ltrs

Trip No	Dump Station		Load Station		Delay to Production Yes / No	Delay Time minutes	Rake No	Reason for Delay	Manual Brake Pipe Continuity Completed (Train Drivers Initials Required)
	Arrival Time	Green Light	Arrival Time	Green Light					
1	0351	0458	0532	0535	Y		3	LP Unloading issues	
2	0610		0643	0658	N		1		TL AR
3	0733		0807	0820	N		2		
4	0855		0926	0938	N		3		
5	1013		1045	1056	NO		1		
6	1131		1202	1213	NO		2		
7	1246		1317	1328	NO		3		
8	1401		1431	1452	NO				
9	1525								
10									
11									
12									

Time of Fault/Delay	Fault/Delay Description	Notification Raised	Notification No.

A Continuity Test must be done before moving the Train after Rake changeover!

Document reviewed and necessary Notifications/Maintenance Orders raised. Crewleader Signature.....

Date 5/1/26 Loco No. R1005 Cab No 2 Facing Andoom Shift Driver/s Rob/Glen Day Night Shift

The following checks are to be performed at shift handover or close as practical

Vigilance Operational	Engine Oil	Radiator Water		End of Rake Marker Operational	Rake Leakage Check kPa
Yes No	Ok Not OK Topped up	OK Not Ok Topped Up		Rake 1 Y N Rake 2 Y N Rake 3 Y N	Rake 1 0 Rake 2 0 Rake 3 0
Loco Comp Oil	OK Not OK Topped Up				

Record time comp car/loco hrs taken			Lead Rake1 2nd	Lead Rake2 2nd	Lead Rake3 2nd	Locomotive
Rake 1		Engine Oil	Comp Car Amt Added	Comp Car Amt Added	Comp Car Amt Added	Comp Car Amt Added
Rake 2		Comp Oil	Comp Car Amt Added	Comp Car Amt Added	Comp Car Amt Added	Comp Car Amt Added
Rake 3		Comp Hrs				Loco Hrs 21972
		Next Service				Cab Cleaned COVID
Locomotive	1540		Running in Auto / Manual Not Running	Running in Auto / Manual Not Running	Running in Auto / Manual Not Running	Loco Km's Travelled 449407
Fuel added to comp cars / Loco			Ltr's	Ltr's	Ltr's	Ltrs

Trip No	Dump Station Arrival Time	Dump Station Green Light	Load Station Arrival Time	Load Station Green Light	Delay to Production Yes / No	Delay Time minutes	Rake No	Reason for Delay	Manual Brake Pipe Continuity Completed (Train Drivers Initials Required)
1	1530		1604	1612			2	MCR 2	GM RA
2	1648		1721	1728			3	MC R 3	RR
3	1806		1837	1845			1	MC R1	RR
4	1921		1954	2019			2	Fuel loco 1000L	
5	2055		2125	2137			3		
6	2213		2245	2257.			1		
7	2352	2348	0015.	0050			2	Fuel loco 2000 Ltrs.	
8	0125.		0155	0215			3		
9	0250,		0318	0342					
10	0417								
11									
12									

Time of Fault/Delay	Fault/Delay Description	Notification Raised	Notification No.
	Eng oil could do with a topup 100 tal down		
	Mic on TOP Radio Rb1 end Works intermittently	Cable?	
	Rake 3 No transit Light on EOR		

A Continuity Test must be done before moving the Train after Rake changeover!

Document reviewed and necessary Notifications/Maintenance Orders raised. Crewleader Signature.....