Date 19/07/2027 Loco No. R1007 Cab No 2 Facing Andoom Shift Driver/s ADAM NEV Day Night Shift

The following checks are to be performed at shift handover or close as practical

Vigilance Operational	Engine Oil	Radiator Water	End of Rake Marker Operational	Rake Leakage Check kPa
Yes No	HGIS Ok Not OK Topped up	OK Not Ok Topped Up	Rake 1 Y N Rake 2 Y N Rake 3 Y N	Rake 1 Rake 2 Rake 3

Loco Comp Oil	Lead	Rake1	2nd	Lead	Rake2	2nd	Lead	Rake3	2nd	Locomotive
2 OK Not OK Topped Up	Comp Car N	Comp Car I		Comp Car K	Comp Car P		Comp Car J	Comp Car M		Radiator Water added(mm s/glass)

Record time comp car/loco hrs taken												
Rake 1	0532	Engine Oil	Amt Added		Amt Added		Amt Added		Amt Added		Amt Added	
Rake 2	0546	Comp Oil	Amt Added		Amt Added		Amt Added		Amt Added		Amt Added	
Rake 3	0420	Comp Hrs	35895		11247		8279	16980	16612	18379	Loco Hrs	
		Next Service	36800		12000		9100	17057	17500	19000	Cab Cleaned COVID	
Locomotive			Running in Auto / Manual Not Running		Running in Auto / Manual Not Running		Running in Auto / Manual Not Running	Running in Auto / Manual Not Running	Running in Auto / Manual Not Running	Running in Auto / Manual Not Running	Loco Km's Travelled	
Fuel added to comp cars / Loco			Ltr's		Ltr's		Ltr's	Ltr's	Ltr's	Ltr's	3000	Ltrs

Trip No	Dump Station		Load Station		Delay to Production Yes / No	Delay Time minutes	Rake No	Reason for Delay	Manual Brake Pipe Continuity Completed (Train Drivers Initials Required)
	Arrival Time	Green Light	Arrival Time	Green Light					
1	0406		0454	0454	N		3	Manual load	
2	0529		0616	0616	N		1	2110 Fail to load	
3	0651	0704	0747	0747	N		2	Dump Delay K comp swap over	
4	0822		0855	0908	N		3		
5	0943		1022	1029	N		1		
6	1106	1114	1212	1214	Y		2	fuel loco, 3000L W/shop fixing comp K	
7	1250	1300	1334	1350	N		3		
8	1425		1505	1511	N		1		
9	1545						2		
10									
11									
12									

Time of Fault/Delay	Fault/Delay Description	Notification Raised	Notification No.

A Continuity Test must be done before moving the Train after Rake changeover!

Document reviewed and necessary Notifications/Maintenance Orders raised. Crewleader Signature.....

Date 19/2/26 Loco No. R1007 Cab No 2 Facing Andoom Shift Driver/s Gary Day Night Shift

The following checks are to be performed at shift handover or close as practical

Vigilance Operational	Engine Oil	Radiator Water	End of Rake Marker Operational	Rake Leakage Check kPa
(Yes) No	(Ok) Not OK Topped up	OK Not Ok Topped Up	Rake 1 (Y) N Rake 2 (Y) N Rake 3 (Y) N	Rake 1 0 Rake 2 0 Rake 3 0

Loco Comp Oil	OK	Not OK	Topped Up

Record time comp car/loco hrs taken			Lead	Rake1	2nd	Lead	Rake2	2nd	Lead	Rake3	2nd	Locomotive
Rake 1		Engine Oil	Comp Car	Comp Car		Comp Car	Comp Car		Comp Car	Comp Car		Radiator Water added(mm s/glass)
Rake 2		Comp Oil	Amt Added	Amt Added		Amt Added	Amt Added		Amt Added	Amt Added		Amt Added
Rake 3		Comp Hrs	Amt Added	Amt Added		Amt Added	Amt Added		Amt Added	Amt Added		Amt Added
		Next Service										Loco Hrs
Locomotive	1900		Running in Auto / Manual Not Running	Running in Auto / Manual Not Running		Running in Auto / Manual Not Running	Running in Auto / Manual Not Running		Running in Auto / Manual Not Running	Running in Auto / Manual Not Running		Cab Cleaned COVID
												Loco Km's Travelled 515142
Fuel added to comp cars / Loco			Ltr's	Ltr's		Ltr's	Ltr's		Ltr's	Ltr's		1500 Ltrs

Trip No	Dump Station Arrival Time	Dump Station Green Light	Load Station Arrival Time	Load Station Green Light	Delay to Production Yes / No	Delay Time minutes	Rake No	Reason for Delay	Manual Brake Pipe Continuity Completed (Train Drivers Initials Required)
1	1600		1634	1639	Yes	~~Yes~~ 20	2	Slow Dumping / 4mins comp repairs	NT GA
2	1712	1718	1747	1755	NO		3		NT GA
3	1828		1903	1913	NO		1		GA Jacob
4	1946	2024		2053	Yes	30		Meal Break ½ hour	
5	2126	2135	2209	2230	NO				
6	2303		2340	2354	NO				
7	0027	0109	0134	0143	Yes			Meal Break ½ hour 1500L	
8	0216		0250	0300	NO				
9	0333								
10									
11									
12									

Time of Fault/Delay	Fault/Delay Description	Notification Raised	Notification No.
	Blinds need Fixing if This loco is out		
	Can not see late after noon or morning from the sun		

A Continuity Test must be done before moving the Train after Rake changeover!

Document reviewed and necessary Notifications/Maintenance Orders raised. Crewleader Signature.....