Date 19/5/21 Loco No. R1005 Cab No 2 Facing Andoom Shift Driver/s Jed Fyfe Day (Night) Shift

The following checks are to be performed at shift handover or close as practical

Vigilance Operational	Engine Oil	Radiator Water		End of Rake Marker Operational			Rake Leakage Check kPa		
(Yes) No	(Ok) Not OK Topped up	(OK) Not Ok Topped Up		Rake 1 (Y) N	Rake 2 (Y) N	Rake 3 (Y) N	Rake 1 0	Rake 2 0	Rake 3 0

Loco Comp Oil	Lead	Rake1	2nd	Lead	Rake2	2nd	Lead	Rake3	2nd	Locomotive
(OK) Not OK Topped Up	Comp Car	Comp Car		Comp Car	Comp Car		Comp Car	Comp Car		Radiator Water added(mm s/glass)
Record time comp car/loco hrs taken	Amt Added	Amt Added		Amt Added	Amt Added		Amt Added	Amt Added		Amt Added
Rake 1 / Engine Oil	Amt Added	Amt Added		Amt Added	Amt Added		Amt Added	Amt Added		Amt Added
Rake 2 / Comp Oil										Loco Hrs 24474
Rake 3 / Comp Hrs										Cab Cleaned COVID
Next Service	Running in Auto / Manual Not Running	Running in Auto / Manual Not Running		Running in Auto / Manual Not Running	Running in Auto / Manual Not Running		Running in Auto / Manual Not Running	Running in Auto / Manual Not Running		Loco Km's Travelled 493222
Locomotive 1710	Ltr's	Ltr's		Ltr's	Ltr's		Ltr's	Ltr's		Ltrs
Fuel added to comp cars / Loco										

Trip No	Dump Station		Load Station		Delay to Production Yes / No	Delay Time minutes	Rake No	Reason for Delay	Manual Brake Pipe Continuity Completed (Train Drivers Initials Required)
	Arrival Time	Green Light	Arrival Time	Green Light					
1	1558		1627	1710	No		3		
2	1745		1814	1850	No		1		
3	1925		1950	2054	No		2		
4	2129		2200	2232			3		
5	2307		2337	0006			1		
6	0041		0110	0150			2		
7	0225		0255	0333			3		
8	0408						1		
9									
10									
11									
12									

Time of Fault/Delay	Fault/Delay Description	Notification Raised	Notification No.

A Continuity Test must be done before moving the Train after Rake changeover!

Document reviewed and necessary Notifications/Maintenance Orders raised. Crewleader Signature.....