Date 19.6.26 Loco No. R1005 Cab No 2 Facing Andoom Shift Driver/s Molly-Trooi Day Night Shift

The following checks are to be performed at shift handover or close as practical

Vigilance Operational	Engine Oil	Radiator Water	End of Rake Marker Operational	Rake Leakage Check kPa
Yes No	Ok Not OK Topped up	OK Not Ok Topped Up	Rake 1 Y N Rake 2 Y N Rake 3 Y N	Rake 1 Rake 2 Rake 3

Loco Comp Oil	OK Not OK Topped Up	Lead	Rake1	2nd	Lead	Rake2	2nd	Lead	Rake3	2nd	Locomotive

Record time comp car/loco hrs taken			Comp Car	Comp Car	Comp Car	Comp Car	Comp Car	Comp Car	Radiator Water added(mm e/glass)
Rake 1		Engine Oil	Amt Added	Amt Added	Amt Added	Amt Added	Amt Added	Amt Added	Amt Added
Rake 2		Comp Oil	Amt Added	Amt Added	Amt Added	Amt Added	Amt Added	Amt Added	Amt Added
Rake 3		Comp Hrs							Loco Hrs
		Next Service							Cab Cleaned COVID
Locomotive			Running In Auto / Manual Not Running	Running In Auto / Manual Not Running	Running In Auto / Manual Not Running	Running In Auto / Manual Not Running	Running In Auto / Manual Not Running	Running In Auto / Manual Not Running	Loco Km's Travelled
Fuel added to comp cars/ Loco			Ltr's	Ltr's	Ltr's	Ltr's	Ltr's	Ltr's	1500 Ltrs

Trip No	Dump Station		Load Station		Delay to Production Yes / No	Delay Time minutes	Rake No	Reason for Delay	Manual Brake Pipe Continuity Completed (Train Drivers Initials Required)
	Arrival Time	Green Light	Arrival Time	Green Light					
1	1618		1703	1710	NO		2	MC	M.M.
2	1745		1813	1846	NO		3	MC	MM.
3	1925		1914	2025	NO		1	MC	MM.
4	2100		2135	2155	NO		2		
5	2235		2303	2328	NO		3		
6	0002		0036	0050	NO		1		
7	0124		0155	0209	NO		2		
8	0243	0257	0339	0341	~~NO~~ Y	20M	3	fuel loco Dump delay stacker move	
9	0415						1		
10									
11									
12									

Time of Fault/Delay	Fault/Delay Description	Notification Raised	Notification No.
	adult on Andoom at bridge. Fire + Emergency attended. He was slow		
	to jump off the bridge (rail side) even when flashing lights/blowing horn		
	Ute with dog cage parked on road side at the time		

A Continuity Test must be done before moving the Train after Rake changeover!

Document reviewed and necessary Notifications/Maintenance Orders raised. Crewleader Signature.....