Date 19.9.26 Loco No. R1007 Cab No 2 Facing Andoom Shift Driver/s TRUDI (Day) Night Shift

The following checks are to be performed at shift handover or close as practical

Vigilance Operational	Engine Oil	Radiator Water	End of Rake Marker Operational	Rake Leakage Check kPa
(Yes) No	(Ok) Not OK Topped up	(OK) Not Ok Topped Up	Rake 1 (Y) N Rake 2 (Y) N Rake 3 (Y) N	Rake 1 0 Rake 2 0 Rake 3 0

Loco Comp Oil ?	OK	Not OK	Topped Up

	Lead	Rake1	2nd	Lead	Rake2	2nd	Lead	Rake3	2nd	Locomotive
Comp Car	F	T		O	K					Radiator Water added(mm s/gless)
Amt Added										Amt Added
Amt Added										Loco Hrs
Comp Hrs	17390	17135		33887	8682					Cab Cleaned COVID
Next Service	18137	17500		34500	9100					Loco Km's Travelled
Running In Auto / Manual (Not Running)	(Running In Auto / Manual) Not Running			(Running In Auto / Manual) Not Running						534554
Ltr's										2170 Ltrs

Record time comp car/loco hrs taken

Rake 1	0428
Rake 2	0558
Rake 3	
Locomotive	0610

Engine Oil / Comp Oil / Comp Hrs / Next Service

Sug added to comp cars / Loco

Trip No	Dump Station Arrival Time	Dump Station Green Light	Load Station Arrival Time	Load Station Green Light	Delay to Production Yes / No	Delay Time minutes	Rake No	Reason for Delay	Manual Brake Pipe Continuity Completed (Train Drivers Initials Required)
1	0430		0505	0518	NO		1		
2	0552		0635	0639	NO		2		
3	0714		0754	0758	NO		3		L + DT
4	0832		0910	0924	NO		1		L + DT
5	0958		1100	1123	NO		2	Crew Break 1010-1040	L + DT
6	1200		1230	1249	NO		3		
7	1325		1358	1414	NO		1	Fuel Loco 2170L	
8	1450						2		
9							3		
10									
11									
12									

Time of Fault/Delay	Fault/Delay Description	Notification Raised	Notification No.
	R3 rail 64 OK ✓		

A Continuity Test must be done before moving the Train after Rake changeover!

Document reviewed and necessary Notifications/Maintenance Orders raised. Crewleader Signature.....