Date 2/2/26 Loco No. R1005 Cab No Facing Andoom Shift Driver/s GARY - NEV Day Night Shift

The following checks are to be performed at shift handover or close as practical

Vigilance Operational	Engine Oil	Radiator Water	End of Rake Marker Operational	Rake Leakage Check kPa
Yes No	Ok Not OK Topped up +10	OK Not Ok Topped Up	Rake 1 Y N Rake 2 Y N Rake 3 Y N	Rake 1 0 Rake 2 0 Rake 3 0
Loco Comp Oil	OK Not OK Topped Up			

Record time comp car/loco hrs taken

			Lead	Rake1	2nd	Lead	Rake2	2nd	Lead	Rake3	2nd	Locomotive
			Comp Car N	Comp Car J		Comp Car P	Comp Car O		Comp Car I	Comp Car M		Radiator Water added(mm s/glass)
Rake 1	0330	Engine Oil	Amt Added	Amt Added		Amt Added	Amt Added		Amt Added	Amt Added		Amt Added
Rake 2	0510	Comp Oil	Amt Added	Amt Added		Amt Added	Amt Added		Amt Added	Amt Added		Amt Added
Rake 3	0630	Comp Hrs	35028	15496		15480	32753		10065	17318		Loco Hrs 22566
		Next Service	35000	15500		16000	33500		11000	18137		Cab Cleaned COVID
Locomotive	0345		Running in Auto / Manual Not Running	Running in Auto / Manual Not Running		Running in Auto / Manual Not Running	Running in Auto / Manual Not Running		Running in Auto / Manual Not Running	Running in Auto / Manual Not Running		Loco Km's Travelled 461994
Fuel added to comp cars / Loco			Ltr's	Ltr's		Ltr's	Ltr's		Ltr's	Ltr's		1600 Ltrs

Trip No	Dump Station Arrival Time	Dump Station Green Light	Load Station Arrival Time	Load Station Green Light	Delay to Production Yes / No	Delay Time minutes	Rake No	Reason for Delay	Manual Brake Pipe Continuity Completed (Train Drivers Initials Required)
1	0341		0413	0434	NO		1		
2	0507		0540	0600	NO		2		
3	0633		0705	0748	NO		3		
4	0820		0852	0939	NO		1		
5	1012		1044	1126	NO		2		
6	1159		1246	1323	NO		3	fuel Loco	
7	1358		1446	1529	NO		1		
8	1604						2		
9									
10									
11									
12									

Time of Fault/Delay	Fault/Delay Description	Notification Raised	Notification No.

A Continuity Test must be done before moving the Train after Rake changeover!

Document reviewed and necessary Notifications/Maintenance Orders raised. Crewleader Signature.....