Date 7/6/26 Loco No. R1007 Cab No 2 Facing Andoom Shift Driver/s TRUDI / GARY ~~Day~~ Night Shift

The following checks are to be performed at shift handover or close as practical

Vigilance Operational	Engine Oil	Radiator Water		End of Rake Marker Operational	Rake Leakage Check kPa
(Yes) No	(Ok) Not OK Topped up	(OK) Not Ok Topped Up		Rake 1 (Y) N Rake 2 (Y) N Rake 3 (Y) N	Rake 1 0 Rake 2 0 Rake 3 0

Loco Comp Oil ?	OK	Not OK	Topped Up	Lead	Rake1	2nd	Lead	Rake2	2nd	Lead	Rake3	2nd	Locomotive

Record time comp car/loco hrs taken			Comp Car	Comp Car	Comp Car	Comp Car	Comp Car	Comp Car	Radiator Water added(mm s/glass)
Rake 1		Engine Oil	Amt Added	Amt Added	Amt Added	Amt Added	Amt Added	Amt Added	Amt Added
Rake 2		Comp Oil	Amt Added	Amt Added	Amt Added	Amt Added	Amt Added	Amt Added	Amt Added
Rake 3		Comp Hrs							Loco Hrs
		Next Service							Cab Cleaned COVID
Locomotive	1815		Running in Auto / Manual Not Running	Running in Auto / Manual Not Running	Running in Auto / Manual Not Running	Running in Auto / Manual Not Running	Running in Auto / Manual Not Running	Running in Auto / Manual Not Running	Loco Km's Travelled 510458.6
Fuel added to comp cars / Loco			Ltr's	Ltr's	Ltr's	Ltr's	Ltr's	Ltr's	Ltrs

Trip No	Dump Station		Load Station		Delay to Production Yes / No	Delay Time minutes	Rake No	Reason for Delay	Manual Brake Pipe Continuity Completed (Train Drivers Initials Required)
	Arrival Time	Green Light	Arrival Time	Green Light					
1	0615		1657	1701			3	replace EOT light R1 at dump stn	+ SW
2	1735	1739	1810	1822	No		1		
3	1856		1928	1940	NO		2		
4	2014		2048	2059	No		3		
5	2133		2204	2217	NO		1		
6	2251		2325	2334	NO		2		
7	0007		0038	0055	NO		3		
8	0128		0200	0212	NO				
9	0245	0255		0327	NO				
10	0400								
11									
12									

Time of Fault/Delay	Fault/Delay Description	Notification Raised	Notification No.

A Continuity Test must be done before moving the Train after Rake changeover!

Document reviewed and necessary Notifications/Maintenance Orders raised. Crewleader Signature.....