Date 8/2/26 Loco No. R1005 Cab No 1 Facing Andoom Shift Drivers ADAM / TRUDY (Day) Night Shift

The following checks are to be performed at shift handover or close as practical

Vigilance Operational	Engine Oil	Radiator Water	End of Rake Marker Operational	Rake Leakage Check kPa
(Yes) No	(Ok) Not OK Topped up	(OK) Not Ok Topped Up	Rake 1 (Y) N Rake 2 (Y) N Rake 3 (Y) N	Rake 1 (0) Rake 2 (0) Rake 3 (0)

Loco Comp Oil	Lead	Rake1	2nd	Lead	Rake2	2nd	Lead	Rake3	2nd	Locomotive
(OK) Not OK Topped Up	Comp Car N	Comp Car K		Comp Car P	Comp Car O		Comp Car I	Comp Car M		Radiator Water added(mm s/glass)
Record time comp car/loco hrs taken	Amt Added	Amt Added		Amt Added	Amt Added		Amt Added	Amt Added		Amt Added
Rake 1 0556 / Engine Oil	Amt Added	Amt Added		Amt Added	Amt Added		Amt Added	Amt Added		Amt Added
Rake 2 0713 / Comp Oil	Amt Added	Amt Added		Amt Added	Amt Added		Amt Added	Amt Added		Amt Added
Rake 3 0350 / Comp Hrs	35062	7232		15533	32800		10117	17366		Loco Hrs 22717
Next Service	35000	8100		16000	33500		11000	18137		Cab Cleaned COVID
Locomotive 1042	Running in Auto / Manual (Not Running)	Running in Auto / Manual (Not Running)		Running in Auto / Manual (Not Running)	Running in Auto / Manual (Not Running)		Running in Auto / Manual (Not Running)	Running in Auto / Manual (Not Running)		Loco Km's Travelled 465003
Fuel added to comp cars / Loco	Ltr's	Ltr's		Ltr's	Ltr's		Ltr's	Ltr's		1800 Ltrs

Trip No	Dump Station Arrival Time	Dump Station Green Light	Load Station Arrival Time	Load Station Green Light	Delay to Production Yes / No	Delay Time minutes	Rake No	Reason for Delay	Manual Brake Pipe Continuity Completed (Train Drivers Initials Required)
1	0430		0510	0534	N		3		JR
2	0609		0648	0923	N		1	ANZOOM one stop FCG	JR
3	0958		1042	1052	N		2	Rake 2 comp O oil leak/tag Swapped to P	D + AR
4	1126		1155	1219	N		3		
5	1254		1325	1343	N		1		
6	1417		1510	1517	N		2		
7	1551						3		
8							1		
9							2		
10									
11									
12									

Time of Fault/Delay	Fault/Delay Description	Notification Raised	Notification No.
	Flats Wagon 15 / R3		
	Dynamic brake - not pulling normal (50-60 only) Amps / sanding icon showing.		
	Restriction removed 2-1E - Norm/Gaurie fixed		

A Continuity Test must be done before moving the Train after Rake changeover!

Document reviewed and necessary Notifications/Maintenance Orders raised. Crewleader Signature.....