Date 8/3/26 Loco No. R1005 Cab No 1 Facing Andoom Shift Driver/s PETE JED Day (Night) Shift

The following checks are to be performed at shift handover or close as practical

Vigilance Operational	Engine Oil	Radiator Water		End of Rake Marker Operational			Rake Leakage Check kPa		
(Yes) No	(Ok) Not OK Topped up	(OK) Not Ok Topped Up		Rake 1 (Y) N	Rake 2 (Y) N	Rake 3 (Y) N	Rake 1 0	Rake 2 0	Rake 3 0

Loco Comp Oil	Lead	Rake1	2nd	Lead	Rake2	2nd	Lead	Rake3	2nd	Locomotive
(OK) Not OK Topped Up	Comp Car	Comp Car		Comp Car	Comp Car		Comp Car	Comp Car		Radiator Water added(mm s/glass)
Record time comp car/loco hrs taken	Amt Added	Amt Added		Amt Added	Amt Added		Amt Added	Amt Added		Amt Added
Rake 1 / Engine Oil	Amt Added	Amt Added		Amt Added	Amt Added		Amt Added	Amt Added		Amt Added
Rake 2 / Comp Oil										Loco Hrs 22723
Rake 3 / Comp Hrs										Cab Cleaned COVID
Next Service										
Locomotive 16:29	Running in Auto / Manual Not Running	Running in Auto / Manual Not Running		Running in Auto / Manual Not Running	Running in Auto / Manual Not Running		Running in Auto / Manual Not Running	Running in Auto / Manual Not Running		Loco Km's Travelled 465160
Fuel added to comp cars / Loco	Ltr's	Ltr's		Ltr's	Ltr's		Ltr's	Ltr's		2000 Ltrs

Trip No	Dump Station		Load Station		Delay to Production Yes / No	Delay Time minutes	Rake No	Reason for Delay	Manual Brake Pipe Continuity Completed (Train Drivers Initials Required)
	Arrival Time	Green Light	Arrival Time	Green Light					
1	1551		1628	1646	N		3		
2	1721		1807	1807	N		1	M/C	PH
3	1842		1918	1943	N		2	M/C	PH
4	2018		2055	2113	N		3	M/C	PH
5	2148		2230	2245	NO		1		
6	2320		2350	0012	NO		2		
7	0047		0117	0137	NO		3		
8	0212		0250	0310	NO		1	Refueled Loco 2000L	
9	0345						2		
10									
11									
12									

Time of Fault/Delay	Fault/Delay Description	Notification Raised	Notification No.

A Continuity Test must be done before moving the Train after Rake changeover!

Document reviewed and necessary Notifications/Maintenance Orders raised. Crewleader Signature.....