Date 8/6/26 Loco No. R1005 Cab No 2 Facing Andoom Shift Driver/s Gary Tzodi Day (Night) Shift

The following checks are to be performed at shift handover or close as practical

Vigilance Operational	Engine Oil	Radiator Water	End of Rake Marker Operational	Rake Leakage Check kPa
(Yes) No	(Ok) Not OK Topped up	(OK) Not Ok Topped Up	Rake 1 (Y) N Rake 2 (Y) N Rake 3 (Y) N	Rake 1 2 Rake 2 0 Rake 3 0

Loco Comp Oil	OK	Not OK	Topped Up

	Lead	Rake1	2nd	Lead	Rake2	2nd	Lead	Rake3	2nd	Locomotive
Record time comp car/loco hrs taken	Comp Car		Comp Car	Comp Car		Comp Car	Comp Car		Comp Car	Comp Car		Radiator Water added(mm s/glass)
Rake 1 / Engine Oil	Amt Added		Amt Added	Amt Added		Amt Added	Amt Added		Amt Added	Amt Added		Amt Added
Rake 2 / Comp Oil	Amt Added		Amt Added	Amt Added		Amt Added	Amt Added		Amt Added	Amt Added		Amt Added
Rake 3 / Comp Hrs												Loco Hrs 24767
Next Service												Cab Cleaned COVID
Locomotive 1617	Running in Auto / Manual Not Running		Running in Auto / Manual Not Running	Running in Auto / Manual Not Running		Running in Auto / Manual Not Running	Running in Auto / Manual Not Running		Running in Auto / Manual Not Running	Running in Auto / Manual Not Running		Loco Km's Travelled 498463
Fuel added to comp cars / Loco	Ltr's		Ltr's	Ltr's		Ltr's	Ltr's		Ltr's	Ltr's		2500 Ltrs

Trip No	Dump Station Arrival Time	Dump Station Green Light	Load Station Arrival Time	Load Station Green Light	Delay to Production Yes / No	Delay Time minutes	Rake No	Reason for Delay	Manual Brake Pipe Continuity Completed (Train Drivers Initials Required)
1	1525		1614	1643	NO		2	Driver do rake change Andoom	
2	1717		1747	1825	NO		3		R
3	1859		1930	1955	NO		1		R
4	2029		2100	2150	NO		2	R1 didnt go into transit(screen) M/C done	R
5	2220		2255	2323	NO		3		
6	2356		2325	0052	NO				
7	0125		0156	0233				* COOLANT LEVEL JUST ABOVE LOW*	
8	0306							Fuel loco	
9									
10									
11									
12									

Time of Fault/Delay	Fault/Delay Description	Notification Raised	Notification No.

A Continuity Test must be done before moving the Train after Rake changeover!

Document reviewed and necessary Notifications/Maintenance Orders raised. Crewleader Signature.....