Date 6/1/26 Loco No. R005 Cab No 2 Facing Andoom Shift Driver/s Rob BLEN Day (Night) Shift

The following checks are to be performed at shift handover or close as practical

Vigilance Operational	Engine Oil	Radiator Water	End of Rake Marker Operational	Rake Leakage Check kPa
(Yes) No	(Ok) Not OK Topped up	(OK) Not Ok Topped Up	Rake 1 (Y) N Rake 2 (Y) N Rake 3 (Y) N	Rake 1 (0) Rake 2 (0) Rake 3 (0)
Loco Comp Oil: (OK) Not OK Topped Up				

Record time comp car/loco hrs taken			Lead	Rake1	2nd	Lead	Rake2	2nd	Lead	Rake3	2nd	Locomotive
Rake 1		Engine Oil	Comp Car / Amt Added	Comp Car / Amt Added		Comp Car / Amt Added	Comp Car / Amt Added		Comp Car / Amt Added	Comp Car / Amt Added		Radiator Water added(mm s/glass) / Amt Added
Rake 2		Comp Oil	Amt Added	Amt Added		Amt Added	Amt Added		Amt Added	Amt Added		Amt Added
Rake 3		Comp Hrs										Loco Hrs 21996
		Next Service										Cab Cleaned COVID
Locomotive	1554		Running in Auto / Manual Not Running	Running in Auto / Manual Not Running		Running in Auto / Manual Not Running	Running in Auto / Manual Not Running		Running in Auto / Manual Not Running	Running in Auto / Manual Not Running		Loco Km's Travelled 450073
Fuel added to comp cars / Loco			Ltr's	Ltr's		Ltr's	Ltr's		Ltr's	Ltr's		2500 Ltrs

Trip No	Dump Station Arrival Time	Dump Station Green Light	Load Station Arrival Time	Load Station Green Light	Delay to Production Yes / No	Delay Time minutes	Rake No	Reason for Delay	Manual Brake Pipe Continuity Completed (Train Drivers Initials Required)
1	1543		1621	1625			1	M/C R1	RR
2	1701		1736	1744			2	mc R2	RR
3	1820		1854	1914			3	MC R3	RR
4	1950		2023	2033			1		
5	2109	2118	2150	2155			2	Roller change LP.	
6	2231		2305	2333			3		
7	0008		0035	0050			1		
8	0125	0137	0203	0209			2	fuelled Loco 1500 LTRS.	
9	0244	0253	0320	0335			3	fuelled Loco 1000 LTRS	
10	0410								
11									
12									

Time of Fault/Delay	Fault/Delay Description	Notification Raised	Notification No.

A Continuity Test must be done before moving the Train after Rake changeover!

Document reviewed and necessary Notifications/Maintenance Orders raised. Crewleader Signature.....

Date 6/1/24 Loco No. R1005 Cab No 2 Facing Andoom Shift Driver/s GARY NEW Day Night Shift

The following checks are to be performed at shift handover or close as practical

Vigilance Operational	Engine Oil	Radiator Water	End of Rake Marker Operational	Rake Leakage Check kPa
Yes No	Ok Not OK Topped up +90	OK Not Ok Topped Up	Rake 1 Y N Rake 2 Y N Rake 3 Y N	Rake 1 Rake 2 Rake 3
Loco Comp Oil	OK Not OK Topped Up			

Record time comp car/loco hrs taken

			Lead	Rake1	2nd	Lead	Rake2	2nd	Lead	Rake3	2nd	Locomotive
Rake 1		Engine Oil	Comp Car N	Comp Car J		Comp Car I	Comp Car M		Comp Car K	Comp Car P		Radiator Water added(mm s/glass)
Rake 2	0410	Comp Oil	Amt Added	Amt Added		Amt Added	Amt Added		Amt Added	Amt Added		Amt Added
Rake 3		Comp Hrs	34740	15369		9995	17100		6932	15197		Loco Hrs 21985
		Next Service	35000	15500		10000	17000		7001	16000		Cab Cleaned COVID
Locomotive	0440		Running in Auto / Manual Not Running	Running in Auto / Manual Not Running		Running in Auto / Manual Not Running	Running in Auto / Manual Not Running		Running in Auto / Manual Not Running	Running in Auto / Manual Not Running		Loco Km's Travelled 449761
Fuel added to comp cars / Loco			Ltr's	Ltr's		Ltr's	Ltr's		Ltr's	Ltr's		Ltrs

Trip No	Dump Station Arrival Time	Dump Station Green Light	Load Station Arrival Time	Load Station Green Light	Delay to Production Yes / No	Delay Time minutes	Rake No	Reason for Delay	Manual Brake Pipe Continuity Completed (Train Drivers Initials Required)
1	0417		0502	0521	NO		2	Fuel loco 1875	
2	0554		0625	0645	NO		3		
3	0718		0753	0807	NO		1		
4	0840		0912	0932	NO		2		
5	1005		1035	1105	NO		3		
6	1138		1210	1221	NO		1		
7	1256		1327	1340	NO		2		
8	1415		1447	1507	NO		3		
9	1543						1		
10									
11									
12									

Time of Fault/Delay	Fault/Delay Description	Notification Raised	Notification No.

A Continuity Test must be done before moving the Train after Rake changeover!

Document reviewed and necessary Notifications/Maintenance Orders raised. Crewleader Signature.....