Date 7.9.26 Loco No. R1007 Cab No 2 Facing Andoom Shift Driver/s Glen-Rob Day / Night Shift

The following checks are to be performed at shift handover or close as practical

Vigilance Operational	Engine Oil	Radiator Water	End of Rake Marker Operational	Rake Leakage Check kPa
Yes / No	Ok / Not OK / Topped up	OK / Not Ok / Topped Up	Rake 1 Y N Rake 2 Y N Rake 3 Y N	Rake 1 0 Rake 2 0 Rake 3 0
Loco Comp Oil	OK / Not OK / Topped Up			

Record time comp car/loco hrs taken			Lead Rake1 2nd	Lead Rake2 2nd	Lead Rake3 2nd	Locomotive
Rake 1	0340	Engine Oil	Comp Car P / Comp Car S	Comp Car O / Comp Car R	Comp Car E / Comp Car M	Radiator Water added(mm s/glass)
Rake 2	0500	Comp Oil	Amt Added / Amt Added	Amt Added / Amt Added	Amt Added / Amt Added	Amt Added / Amt Added
Rake 3	0020	Comp Hrs	17311 / 17016	33787 / 8580	11528 / 18800	Loco Hrs 7491
		Next Service	18137 / 17500	34500 / 9100	12000 / 19000	Cab Cleaned: COVID
Locomotive	0345		Running In Auto / ~~Manual~~ Not Running / Running In Auto / ~~Manual~~ ~~Not Running~~	Running In Auto / ~~Manual~~ Not Running / Running In Auto / ~~Manual~~ ~~Not Running~~	~~Running In Auto / Manual~~ Not Running / Running In Auto / ~~Manual~~ ~~Not Running~~	Loco Km's Travelled 528669
Fuel added to comp cars / Loco			Ltr's / Ltr's	Ltr's / Ltr's	Ltr's / Ltr's	Ltrs

Trip No	Dump Station		Load Station		Delay to Production Yes / No	Delay Time minutes	Rake No	Reason for Delay	Manual Brake Pipe Continuity Completed (Train Drivers Initials Required)
	Arrival Time	Green Light	Arrival Time	Green Light					
1	0340		0413	0426			1		AK
2	0501		0555	0559			2		RR
3	0634		0705	0733			3		
4	0808		0840	0910			1		
5	0945	1140	1205	1205			2	Recycle loco to Andoom	
6	1240		1320	1355			3	Fuel loco 1400L	
7	1431		1503	1545			1		
8	1621						2		
9									
10									
11									
12									

Time of Fault/Delay	Fault/Delay Description	Notification Raised	Notification No.

A Continuity Test must be done before moving the Train after Rake changeover!

Document reviewed and necessary Notifications/Maintenance Orders raised. Crewleader Signature.....

Date 7/9/26 Loco No. 7 Cab No 2 Facing Andoom Shift Driver/s Jed / Pete / Steve Day (Night) Shift

The following checks are to be performed at shift handover or close as practical

Vigilance Operational	Engine Oil	Radiator Water	End of Rake Marker Operational	Rake Leakage Check kPa
(Yes) No	(Ok) Not OK Topped up	(OK) Not Ok Topped Up	Rake 1 (Y) N Rake 2 (Y) N Rake 3 (Y) N	Rake 1 0 Rake 2 0 Rake 3 0
Loco Comp Oil ? (OK) Not OK Topped Up				

	Lead	Rake1	2nd	Lead	Rake2	2nd	Lead	Rake3	2nd	Locomotive
Record time comp car/loco hrs taken	Comp Car	Comp Car		Comp Car	Comp Car		Comp Car	Comp Car		Radiator Water added(mm s/glass)
Rake 1	Amt Added	Amt Added		Amt Added	Amt Added		Amt Added	Amt Added		Amt Added
Rake 2	Amt Added	Amt Added		Amt Added	Amt Added		Amt Added	Amt Added		Amt Added
Rake 3										Loco Hrs
										Cab Cleaned COVID
Locomotive	Running in Auto / Manual Not Running	Running in Auto / Manual Not Running		Running in Auto / Manual Not Running	Running in Auto / Manual Not Running		Running in Auto / Manual Not Running	Running in Auto / Manual Not Running		Loco Km's Travelled
Fuel added to comp cars / Loco	Ltr's	Ltr's		Ltr's	Ltr's		Ltr's	Ltr's		Ltrs

Trip No	Dump Station		Load Station		Delay to Production Yes / No	Delay Time minutes	Rake No	Reason for Delay	Manual Brake Pipe Continuity Completed (Train Drivers Initials Required)
	Arrival Time	Green Light	Arrival Time	Green Light					
1	1621		1656	1723	No		2		
2	1758		1832	1910	No		3		SH
3	1945		2200	2248	N		1	Fuel Loco 1000L	SH
4	2323		2355	0018	N		2		SH
5	0053		0125	0149	N		3		
6	0224			0325	N		1		
7	0400						2		
8							3		
9									
10									
11									
12									

Time of Fault/Delay	Fault/Delay Description	Notification Raised	Notification No.

A Continuity Test must be done before moving the Train after Rake changeover!

Document reviewed and necessary Notifications/Maintenance Orders raised. Crewleader Signature.....