Date 8/5/26 Loco No. R1065 Cab No 2 Facing Andoom Shift Driver/s Pete/Joel/Molly (Day) Night Shift

The following checks are to be performed at shift handover or close as practical

Vigilance Operational	Engine Oil	Radiator Water	End of Rake Marker Operational	Rake Leakage Check kPa
(Yes) No	(Ok) Not OK Topped up	(OK) Not Ok Topped Up	Rake 1 (Y) N Rake 2 (Y) N Rake 3 (Y) N	Rake 1 0 Rake 2 0 Rake 3 0
Loco Comp Oil: (OK) Not OK Topped Up				

Record time comp car/loco hrs taken			Lead	Rake1	2nd	Lead	Rake2	2nd	Lead	Rake3	2nd	Locomotive
			Comp Car J	Comp Car O		Comp Car P	Comp Car N		Comp Car K	Comp Car M		Radiator Water added(mm s/glass)
Rake 1	0405	Engine Oil	Amt Added	Amt Added		Amt Added	Amt Added		Amt Added	Amt Added		Amt Added
Rake 2	0532	Comp Oil	Amt Added	Amt Added		Amt Added	Amt Added		Amt Added	Amt Added		Amt Added
Rake 3	0654	Comp Hrs	16058	32936		16264	35613		7972	17980		Loco Hrs 24222
		Next Service	16500	33500		17057	36052		8100	18137		Cab Cleaned COVID
Locomotive	0410		Running in Auto / ~~Manual~~ ~~Not Running~~	~~Running in Auto / Manual~~ Not Running		~~Running in Auto / Manual~~ Not Running	Running in Auto / ~~Manual~~ ~~Not Running~~		Running in Auto / ~~Manual~~ ~~Not Running~~	~~Running in Auto / Manual~~ Not Running		Loco Km's Travelled 488929
Fuel added to comp cars / Loco			Ltr's	Ltr's		Ltr's	Ltr's		Ltr's	Ltr's		1300 Ltrs

Trip No	Dump Station Arrival Time	Dump Station Green Light	Load Station Arrival Time	Load Station Green Light	Delay to Production Yes / No	Delay Time minutes	Rake No	Reason for Delay	Manual Brake Pipe Continuity Completed (Train Drivers Initials Required)
1	0254		0402	0416	N		1		
2	0451		0528	0623	N		2	m/c	PH
3	0658		0736	0818	N		3	m/c	PH
4	0853		0934	1010	N		1	m/c	PH
5	1045		1140	1208			2		
6	1243		1315	1410			3	R1, FLATS, 76, 54, 02.	
7	1445						1	REFUEL LOCO	
8								R3, FLATS, 43, 28.	
9									
10									
11									
12									

Time of Fault/Delay	Fault/Delay Description	Notification Raised	Notification No.

A Continuity Test must be done before moving the Train after Rake changeover!

Document reviewed and necessary Notifications/Maintenance Orders raised. Crewleader Signature.....

Date 8/6/26 Loco No. R1005 Cab No 2 Facing Andoom Shift Drivers ROB GOBEN ~~Day~~ Night Shift

"The following checks are to be performed at shift handover or close as practical"

Vigilance Operational	Engine Oil	Radiator Water	End of Rake Marker Operational	Rake Leakage Check kPa
(Yes) No	(Ok) Not OK Topped up	(OK) Not Ok Topped Up	Rake 1 (Y) N Rake 2 (Y) N Rake 3 (Y) N	Rake 1 0 Rake 2 0 Rake 3 0

Loco Comp Oil	Lead	Rake1	2nd	Lead	Rake2	2nd	Lead	Rake3	2nd	Locomotive
(OK) Not OK Topped Up	Comp Car	Comp Car		Comp Car	Comp Car		Comp Car	Comp Car		Radiator Water added(mm s/glass)

Record time comp car/loco hrs taken			Comp Car Amt Added	Comp Car Amt Added	Comp Car Amt Added	Comp Car Amt Added	Comp Car Amt Added	Comp Car Amt Added	Amt Added
Rake 1		Engine Oil	Amt Added	Amt Added	Amt Added	Amt Added	Amt Added	Amt Added	Amt Added
Rake 2		Comp Oil	Amt Added	Amt Added	Amt Added	Amt Added	Amt Added	Amt Added	Loco Hrs 24234
Rake 3		Comp Hrs							Cab Cleaned COVID
		Next Service							Loco Km's Travelled
Locomotive	1604		Running In Auto / Manual Not Running	Running In Auto / Manual Not Running	Running In Auto / Manual Not Running	Running In Auto / Manual Not Running	Running In Auto / Manual Not Running	Running In Auto / Manual Not Running	489164
Fuel added to comp cars// Loco			Ltr's	Ltr's	Ltr's	Ltr's	Ltr's	Ltr's	1500 - Ltrs

Trip No	Dump Station Arrival Time	Dump Station Green Light	Load Station Arrival Time	Load Station Green Light	Delay to Production Yes / No	Delay Time minutes	Rake No	Reason for Delay	Manual Brake Pipe Continuity Completed (Train Drivers Initials Required)
1	1445		1602	1623			1		
2	1659		1731	1840			2	MCR2	RR
3	1916		1948	2030			3	MCR3	RR
4	2106		2138	2219			1	MCR1	RR
5	2255		2320	0037			2		
6	0112		0140	0237			3		
7	0312						1	Loco fuelled 1500 Ltrs.	
8									
9									
10									
11									
12									

Time of Fault/Delay	Fault/Delay Description	Notification Raised	Notification No.

A Continuity Test must be done before moving the Train after Rake changeover!

Document reviewed and necessary Notifications/Maintenance Orders raised. Crewleader Signature.....