Date 9/3/26 Loco No. R1005 Cab No 2 Facing Andoom Shift Driver/s NEV-CARY Day (Night) Shift

The following checks are to be performed at shift handover or close as practical

Vigilance Operational	Engine Oil	Radiator Water	End of Rake Marker Operational	Rake Leakage Check kPa
(Yes) No	(Ok) Not OK Topped up	(OK) Not Ok Topped Up	Rake 1 (Y) N Rake 2 (Y) N Rake 3 (Y) N	Rake 1 (0) Rake 2 (0) Rake 3 (0)
Loco Comp Oil: (Ok) Not OK Topped Up				

Record time comp car/loco hrs taken			Lead Rake1 2nd	Lead Rake2 2nd	Lead Rake3 2nd	Locomotive
Rake 1		Engine Oil	Comp Car: Amt Added / Comp Car: Amt Added	Comp Car: Amt Added / Comp Car: Amt Added	Comp Car: Amt Added / Comp Car: Amt Added	Radiator Water added(mm s/glass) / Amt Added
Rake 2		Comp Oil	Amt Added / Amt Added	Amt Added / Amt Added	Amt Added / Amt Added	Amt Added
Rake 3		Comp Hrs				Loco Hrs 23305
		Next Service				Cab Cleaned COVID
Locomotive	1840		Running in Auto / Manual Not Running	Running in Auto / Manual Not Running	Running in Auto / Manual Not Running	Loco Km's Travelled 475454
Fuel added to comp cars / Loco			Ltr's / Ltr's	Ltr's / Ltr's	Ltr's / Ltr's	1850 Ltrs

Trip No	Dump Station Arrival Time	Dump Station Green Light	Load Station Arrival Time	Load Station Green Light	Delay to Production Yes / No	Delay Time minutes	Rake No	Reason for Delay	Manual Brake Pipe Continuity Completed (Train Drivers Initials Required)
1	1425		1605	1620	NO		2		
2	1650		1720	1805	NO		3		
3	1838		1908	2048	NO		1		
4	2121		2203	2335	NO		2		
5	0008		0048	0215			3	RK3 swap Comp over @ Anloom	
6	0250						1	fuel loco	
7									
8									
9									
10									
11									
12									

Time of Fault/Delay	Fault/Delay Description	Notification Raised	Notification No.

A Continuity Test must be done before moving the Train after Rake changeover!

Document reviewed and necessary Notifications/Maintenance Orders raised. Crewleader Signature.....