Date 9/5/26 Loco No. R1005 Cab No 2 Facing Andoom Shift Driver/s Steve Jed Pete Molly (Day) Night Shift

The following checks are to be performed at shift handover or close as practical

Vigilance Operational	Engine Oil	Radiator Water	End of Rake Marker Operational	Rake Leakage Check kPa
(Yes) No	Ok Not OK Topped up	OK Not Ok Topped Up	Rake 1 Y N Rake 2 Y N Rake 3 Y N	Rake 1 Rake 2 Rake 3
Loco Comp Oil	OK Not OK Topped Up			

Record time comp car/loco hrs taken

			Lead	Rake1	2nd	Lead	Rake2	2nd	Lead	Rake3	2nd	Locomotive
Rake 1	07:54	Engine Oil	Comp Car J	Comp Car O		Comp Car P	Comp Car N		Comp Car K	Comp Car M		Radiator Water added(mm sigless)
Rake 2	07:40	Comp Oil	Amt Added	Amt Added		Amt Added	Amt Added		Amt Added	Amt Added		Amt Added
Rake 3	05:35	Comp Hrs	16073	32936		16264	35628		7987	17980		Loco Hrs
		Next Service	16500	33500		17057	36052		8100	18137		Cab Cleaned COVID
Locomotive			Running In Auto / Manual (Not Running)	Running In Auto / Manual (Not Running)		Running In Auto / Manual (Not Running)	Running In Auto / Manual (Not Running)		Running In Auto / Manual Not Running	Running In Auto / Manual (Not Running)		Loco Km's Travelled
Fuel added to comp cars / Loco			Ltr's	Ltr's		Ltr's	Ltr's		Ltr's	Ltr's		Ltrs

Trip No	Dump Station Arrival Time	Dump Station Green Light	Load Station Arrival Time	Load Station Green Light	Delay to Production Yes / No	Delay Time minutes	Rake No	Reason for Delay	Manual Brake Pipe Continuity Completed (Train Drivers Initials Required)
1	0315		0405	0448			1	M/C	PH
2	0523		0605	0652			2	M/C	PH
3	0727		0759	0855			3	M/C	PH
4	0930		1000	1055			1		
5	1130		1244	1254	N		2		
6	1330		1359	1504	N		3	COMP J SHUTTING DOWN HIGH COMP TEMP.	
7	1540						1		
8							2		
9							3		
10									
11									
12									

Time of Fault/Delay	Fault/Delay Description	Notification Raised	Notification No.

A Continuity Test must be done before moving the Train after Rake changeover!

Document reviewed and necessary Notifications/Maintenance Orders raised. Crewleader Signature.....

Date 9/8/26 Loco No. R1005 Cab No 2 Facing Andoom Shift Drivers ROD / GLEN Day (Night) Shift

The following checks are to be performed at shift handover or close as practical

Vigilance Operational	Engine Oil	Radiator Water	End of Rake Marker Operational	Rake Leakage Check kPa
(Yes) No	(Ok) Not OK Topped up	(OK) Not Ok Topped Up	Rake 1 (Y) N Rake 2 (Y) N Rake 3 (Y) N	Rake 1 0 Rake 2 0 Rake 3 0

Loco Comp Oil	Lead	Rake1	2nd	Lead	Rake2	2nd	Lead	Rake3	2nd	Locomotive
(OK) Not OK Topped Up	Comp Car	Comp Car		Comp Car	Comp Car		Comp Car	Comp Car		Radiator Water added(nm e/gless)

Record time comp car/loco hrs taken		Comp Car	Comp Car	Comp Car	Comp Car	Comp Car	Comp Car	
Rake 1		Engine Oil	Amt Added	Amt Added	Amt Added	Amt Added	Amt Added	Amt Added	Amt Added
Rake 2		Comp Oil	Amt Added	Amt Added	Amt Added	Amt Added	Amt Added	Amt Added	Amt Added
Rake 3		Comp Hrs							Loco Hrs 24258
		Next Service							Cab Cleaned (COVID)
Locomotive	1624		Running In Auto / Manual Not Running	Running In Auto / Manual Not Running	Running In Auto / Manual Not Running	Running In Auto / Manual Not Running	Running In Auto / Manual Not Running	Running In Auto / Manual Not Running	Loco Km's Travelled 489635
Fuel added to comp cars / Loco			Ltr's	Ltr's	Ltr's	Ltr's	Ltr's	Ltr's	Ltrs

Trip No	Dump Station Arrival Time	Dump Station Green Light	Load Station Arrival Time	Load Station Green Light	Delay to Production Yes / No	Delay Time minutes	Rake No	Reason for Delay	Manual Brake Pipe Continuity Completed (Train Drivers Initials Required)
1	1540		1623	1712			1	M/C	RR.
2	1748		1821	1922			2	MCR2	RR
3	1958		2030	2142			3	MCR3	RR
4	2218	2233	2300	0020			1	Rake 1 Not showing transit on screen	MC.
5	0055.		0145	0350			2		
6	0425						3		
7									
8									
9									
10									
11									
12									

Time of Fault/Delay	Fault/Delay Description	Notification Raised	Notification No.
	Shut 3 down keeps tripping on high comp temp		
	"0" running R1.		

A Continuity Test must be done before moving the Train after Rake changeover!

Document reviewed and necessary Notifications/Maintenance Orders raised. Crewleader Signature...