Date 9 / 7 / 2026 Loco No. R1007 Cab No 2 Facing Andoom Shift Driver/s ADAM ~~Geddes~~ New Day / Night Shift

The following checks are to be performed at shift handover or close as practical

Vigilance Operational	Engine Oil	Radiator Water	End of Rake Marker Operational	Rake Leakage Check kPa
(Yes) / No	under Half ↓ (Ok) / Not OK / Topped up	(OK) / Not Ok / Topped Up	Rake 1 (Y) N Rake 2 (Y) N Rake 3 (Y) N	Rake 1 1 Rake 2 0 Rake 3 0
Loco Comp Oil: ? OK / Not OK / Topped Up				

	Lead	Rake1	2nd	Lead	Rake2	2nd	Lead	Rake3	2nd	Locomotive
Record time comp car/loco hrs taken	Comp Car I	Comp Car O		Comp Car P	Comp Car K		Comp Car J	Comp Car M		Radiator Water added(mm s/glass)
Rake 1 0335	Engine Oil Amt Added —	Amt Added 30		Amt Added —	Amt Added 20pumps		Amt Added 30	Amt Added 30		Amt Added
Rake 2 0345	Comp Oil Amt Added	Amt Added		Amt Added	Amt Added		Amt Added	Amt Added		Amt Added
Rake 3 0550	Comp Hrs 11204	33403		16833	8262		16495	18337		Loco Hrs
	Next Service 12000	33500		17057	9100		17500	19000		Cab Cleaned COVID
Locomotive 0603	Running in Auto / Manual (Not Running)	Running in Auto / Manual Not Running		Running in Auto / Manual Not Running	Running in Auto / Manual (Not Running)		Running in Auto / Manual Not Running	Running in Auto / Manual (Not Running)		Loco Km's Travelled 51456.8
Fuel added to comp cars / Loco	120 Ltr's	108 Ltr's		123 Ltr's	85 Ltr's		Ltr's	Ltr's		1700 Ltrs

Trip No	Dump Station Arrival Time	Dump Station Green Light	Load Station Arrival Time	Load Station Green Light	Delay to Production Yes / No	Delay Time minutes	Rake No	Reason for Delay	Manual Brake Pipe Continuity Completed (Train Drivers Initials Required)
1	0342		0427	0435	N		1		
2	0510		0600	0620	N		2	Comp car K not running real well	
3	0655		0749	0808	N		3	" " M "	
4	0843		1111	1223	N		1	1700L Fuel, Andoom Down	
5	1258		1342	1348	N		2		
6	1423		1504	1512	N		3		
7	1548						1		
8							2		
9							3		
10									
11									
12									

Time of Fault/Delay	Fault/Delay Description	Notification Raised	Notification No.
0600	Loco oil under half		
	Comp car K R3 and M R2 not working properly both not pumping air real good + sound like crap		

A Continuity Test must be done before moving the Train after Rake changeover!

Document reviewed and necessary Notifications/Maintenance Orders raised. Crewleader Signature.....

Date 10.7.26 Loco No. 7 Cab No 2 Facing Andoom Shift Driver/s New / Adam Day (Night) Shift

The following checks are to be performed at shift handover or close as practical

Vigilance Operational	Engine Oil	Radiator Water	End of Rake Marker Operational	Rake Leakage Check kPa
(Yes) No	(OK) Not OK Topped up	(OK) Not Ok Topped Up	Rake 1 (Y) N Rake 2 (Y) N Rake 3 (Y) N	Rake 1 Rake 2 (0) Rake 3

Loco Comp Oil 7	OK	Not OK	Topped Up

Record time comp car/loco hrs taken		Lead	Rake1	2nd	Lead	Rake2	2nd	Lead	Rake3	2nd	Locomotive
Rake 1		Engine Oil	Comp Car Amt Added	Comp Car Amt Added	Comp Car Amt Added	Comp Car Amt Added	Comp Car Amt Added	Comp Car Amt Added	Comp Car Amt Added	Comp Car Amt Added	Radiator Water added(mm s/glass) Amt Added
Rake 2		Comp Oil	Amt Added	Amt Added	Amt Added	Amt Added	Amt Added	Amt Added	Amt Added	Amt Added	Amt Added
Rake 3		Comp Hrs									Loco Hrs
		Next Service									Cab Cleaned (COVID)
Locomotive	1732		Running In Auto / Manual Not Running	Running In Auto / Manual Not Running	Running In Auto / Manual Not Running	Running In Auto / Manual Not Running	Running In Auto / Manual Not Running	Running In Auto / Manual Not Running	Running In Auto / Manual Not Running	Running In Auto / Manual Not Running	Loco Km's Travelled
Fuel added to comp cars / Locos			Ltr's	Ltr's	Ltr's	Ltr's	Ltr's	Ltr's	Ltr's	Ltr's	2605 Ltrs

Trip No	Dump Station Arrival Time	Dump Station Green Light	Load Station Arrival Time	Load Station Green Light	Delay to Production Yes / No	Delay Time minutes	Rake No	Reason for Delay	Manual Brake Pipe Continuity Completed (Train Drivers Initials Required)
1	1537		1614	1618	NO		3	MCR3	RD
2	1653		1731	1737	NO		1	R1	
3	1812		1848	1857	Y		2	Vigilance test R2	
4	1928		2007	2025	NO		3		
5	2100		2136	2148	NO		1		
6	2223		2303	2311	N		2		
7	2346		0018	0033	N		3		
8	0108		0143	0203	N		1		
9	0238		0331	0332	Y		2	2600L fuel	
10	0407						3		
11									
12									

Time of Fault/Delay	Fault/Delay Description	Notification Raised	Notification No.
1735	Loco oil needs Topped up		

A Continuity Test must be done before moving the Train after Rake changeover!

Document reviewed and necessary Notifications/Maintenance Orders raised. Crewleader Signature.....