Date 31/3/26 Loco No. R007 Cab No 1 Facing Andoom Shift Driver/s Nev Gary Mike Day Night Shift

The following checks are to be performed at shift handover or close as practical

Vigilance Operational	Engine Oil	Radiator Water		End of Rake Marker Operational	Rake Leakage Check kPa		
Yes No	OK Not OK Topped up	OK Not Ok Topped Up		Rake 1 Y N Rake 2 Y N Rake 3 Y N	Rake 1	Rake 2	Rake 3
Loco Comp Oil	OK Not OK Topped Up	Lead	Rake1 2nd	Lead Rake2 2nd	Lead Rake3 2nd		Locomotive

Record time comp car/loco hrs taken			Comp Car J	Comp Car K	Comp Car O	Comp Car N	Comp Car I	Comp Car M	Radiator Water added(mm s/glass)
Rake 1	0420	Engine Oil	Amt Added	Amt Added	Amt Added	Amt Added	Amt Added	Amt Added	Amt Added
Rake 2	0700	Comp Oil	Amt Added	Amt Added	Amt Added	Amt Added	Amt Added	Amt Added	Amt Added
Rake 3	1000	Comp Hrs	15763	7687	32817	35272	10515	17669	Loco Hrs
		Next Service	16500	8100	33500	36000	11000	18137	Cab Cleaned COVID
Locomotive			Running in Auto / Manual Not Running	Running in Auto / Manual Not Running	Running in Auto / Manual Not Running	Running in Auto / Manual Not Running	Running In Auto / Manual Not Running	Running in Auto / Manual Not Running	Loco Km's Travelled
Fuel added to comp cars / Loco			Ltr's	Ltr's	Ltr's	Ltr's	Ltr's	Ltr's	1256 Ltrs

Trip No	Dump Station Arrival Time	Dump Station Green Light	Load Station Arrival Time	Load Station Green Light	Delay to Production Yes / No	Delay Time minutes	Rake No	Reason for Delay	Manual Brake Pipe Continuity Completed (Train Drivers Initials Required)
1	0455		0505	0635	NO		1		
2	0710		0745	0924	NO		2		
3	0958		1030	1135	NO		3		
4	1208		1235	1345	NO		1		
5	1415		1501	1604	NO		2	Fuel loco	
6	1637						3		
7									
8									
9									
10									
11									
12									

Time of Fault/Delay	Fault/Delay Description	Notification Raised	Notification No.

A Continuity Test must be done before moving the Train after Rake changeover!

Document reviewed and necessary Notifications/Maintenance Orders raised. Crewleader Signature.....

Date 30 / 3 / 26 Loco No. R1007 Cab No 1 Facing Andoom Shift Driver/s Rob/Glen Day Night Shift

The following checks are to be performed at shift handover or close as practical

Vigilance Operational	Engine Oil	Radiator Water		End of Rake Marker Operational	Rake Leakage Check kPa
Yes / No	Ok / Not OK / Topped up	OK / Not Ok / Topped Up		Rake 1 Y N Rake 2 Y N Rake 3 Y N	Rake 1 / Rake 2 / Rake 3
Loco Comp Oil	OK / Not OK / Topped Up				

	Lead	Rake1	2nd	Lead	Rake2	2nd	Lead	Rake3	2nd	Locomotive
Record time comp car/loco hrs taken										
Rake 1										
Rake 2										
Rake 3										
Locomotive 1712										
Engine Oil	Comp Car Amt Added	Comp Car Amt Added		Comp Car Amt Added	Comp Car Amt Added		Comp Car Amt Added	Comp Car Amt Added		Radiator Water added(mm s/glass) Amt Added
Comp Oil	Amt Added	Amt Added		Amt Added	Amt Added		Amt Added	Amt Added		Amt Added
Comp Hrs										Loco Hrs
Next Service										Cab Cleaned COVID
	Running in Auto / Manual Not Running	Running in Auto / Manual Not Running		Running in Auto / Manual Not Running	Running in Auto / Manual Not Running		Running in Auto / Manual Not Running	Running in Auto / Manual Not Running		Loco Km's Travelled 491344
Fuel added to comp cars / Loco	Ltr's	Ltr's		Ltr's	Ltr's		Ltr's	Ltr's		Ltrs

Trip No	Dump Station Arrival Time	Dump Station Green Light	Load Station Arrival Time	Load Station Green Light	Delay to Production Yes / No	Delay Time minutes	Rake No	Reason for Delay	Manual Brake Pipe Continuity Completed (Train Drivers Initials Required)
1	1637		1711	1810			3	MC R3	RR
2	1846		1922	2040			1	MC R1	RR
3	2116		2150	2245			2	MC R2	RR
4	2321		2355	0055			3		
5	0130		0205	0346			1		
6	0341						2		
7							3		
8									
9									
10									
11									
12									

Time of Fault/Delay	Fault/Delay Description	Notification Raised	Notification No.

A Continuity Test must be done before moving the Train after Rake changeover!

Document reviewed and necessary Notifications/Maintenance Orders raised. Crewleader Signature.....