Date 31/7/26 Loco No. R1005 Cab No 1 Facing Andoom Shift Driver/s STEVE JOE (Day) Night Shift

The following checks are to be performed at shift handover or close as practical

Vigilance Operational	Engine Oil	Radiator Water	End of Rake Marker Operational	Rake Leakage Check kPa
(Yes) No	(Ok) Not OK Topped up ↓ 80	(OK) Not Ok Topped Up	Rake 1 Y N Rake 2 Y N Rake 3 Y N	Rake 1 Rake 2 0 Rake 3 0

Loco Comp Oil	Rake 3		Rake 2		Rake 1		Locomotive
(OK) Not OK Topped Up	Lead	2nd	Lead	2nd	Lead	2nd	

Record time comp car/loco hrs taken			Rake 3 Comp Car J	Rake 3 Comp Car M	Rake 2 Comp Car P	Rake 2 Comp Car K	Rake 1 Comp Car I	Rake 1 Comp Car N	Locomotive
Rake 1	07:27	Engine Oil	Amt Added	Amt Added	Amt Added	Amt Added	Amt Added	Amt Added	Radiator Water added(mm s/glass) Amt Added
Rake 2	07:20	Comp Oil	Amt Added	Amt Added	Amt Added	Amt Added	Amt Added	Amt Added	Amt Added
Rake 3	05:51	Comp Hrs	16718	18462	17102	8340	11334	35984	Loco Hrs 25489
		Next Service	17500	19000	17057	9100	12000	36800	Cab Cleaned COVID
Locomotive	08:05		Running in Auto / Manual (Not Running)	Running in Auto / Manual Not Running	(Running in Auto) / Manual Not Running	Running in Auto / Manual (Not Running)	Running in Auto / Manual Not Running	Running in Auto / Manual (Not Running)	Loco Km's Travelled 515498
Fuel added to comp cars / Loco			Ltr's	Ltr's	Ltr's	Ltr's	Ltr's	Ltr's	3500 Ltrs

Trip No	Dump Station Arrival Time	Dump Station Green Light	Load Station Arrival Time	Load Station Green Light	Delay to Production Yes / No	Delay Time minutes	Rake No	Reason for Delay	Manual Brake Pipe Continuity Completed (Train Drivers Initials Required)
1	0400		0440	0519			2		
2	0554		0625	0650			3		SRW JP
3	0725		0755	0820			1		SRW
4	0855		0925	0943			2		SRW
5	1018		1057	1104	No		3	Loco Fuel 2000L	
6	1139		1207	1225	No		1		
7	1300		1329	1350	No		2	EW Plant Down	
8	1425			1520	Yes		3	Loco Fuel 1500L	
9	1555						1		
10									
11									
12									

Time of Fault/Delay	Fault/Delay Description	Notification Raised	Notification No.

A Continuity Test must be done before moving the Train after Rake changeover!

Document reviewed and necessary Notifications/Maintenance Orders raised. Crewleader Signature.....

Date 31/7/26 Loco No. R1005 Cab No 1 Facing Andoom Shift Driver/s Rob Glen Day (Night) Shift

The following checks are to be performed at shift handover or close as practical

Vigilance Operational	Engine Oil	Radiator Water	End of Rake Marker Operational	Rake Leakage Check kPa
(Yes) No	(Ok) Not OK Topped up	(OK) Not Ok Topped Up	Rake 1 (Y) N Rake 2 (Y) N Rake 3 (Y) N	Rake 1 ( ) Rake 2 ( ) Rake 3 ( )
Loco Comp Oil	(OK) Not OK Topped Up			

Record time comp car/loco hrs taken			Lead	Rake1	2nd	Lead	Rake2	2nd	Lead	Rake3	2nd	Locomotive
			Comp Car	Comp Car		Comp Car	Comp Car		Comp Car	Comp Car		Radiator Water added(mm s/glass)
Rake 1		Engine Oil	Amt Added	Amt Added		Amt Added	Amt Added		Amt Added	Amt Added		Amt Added
Rake 2		Comp Oil	Amt Added	Amt Added		Amt Added	Amt Added		Amt Added	Amt Added		Amt Added
Rake 3		Comp Hrs										Loco Hrs 25497
		Next Service										Cab Cleaned COVID
Locomotive	1604		Running In Auto / Manual Not Running	Running In Auto / Manual Not Running		Running In Auto / Manual Not Running	Running In Auto / Manual Not Running		Running In Auto / Manual Not Running	Running In Auto / Manual Not Running		Loco Km's Travelled 515714
Fuel added to comp cars / Loco			Ltr's	Ltr's		Ltr's	Ltr's		Ltr's	Ltr's		2500 Ltrs

Trip No	Dump Station		Load Station		Delay to Production Yes / No	Delay Time minutes	Rake No	Reason for Delay	Manual Brake Pipe Continuity Completed (Train Drivers Initials Required)
	Arrival Time	Green Light	Arrival Time	Green Light					
1	1555		1634	1647			1	MC R1	RR
2	1723		1755	1806			2	MC R2	RR
3	1842		1915	1939			3	MC R3	RR
4	2015		2046	2105			1		
5	2141		2211	2235			2		
6	2311		2340	0001			3		
7	0036	0045	0110	0131			1	Fuelled Loco 1000 Ltrs	
8	0207	0325	0350	0358			2	Fuelled Loco 1500 Ltrs	
9	0433						3		
10									
11									
12									

Time of Fault/Delay	Fault/Delay Description	Notification Raised	Notification No.
	2054 R1 Flats		

A Continuity Test must be done before moving the Train after Rake changeover!

Document reviewed and necessary Notifications/Maintenance Orders raised. Crewleader Signature.....