Date 5/6/26 Loco No. R1005 Cab No 2 Facing Andoom Shift Driver/s JAD STOVE Day ~~Night~~ Shift

The following checks are to be performed at shift handover or close as practical

Vigilance Operational	Engine Oil	Radiator Water		End of Rake Marker Operational	Rake Leakage Check kPa
(Yes) No	Ok Not OK Topped up	OK Not Ok Topped Up		Rake 1 Y N Rake 2 Y N Rake 3 Y N	Rake 1 Rake 2 Rake 3
Loco Comp Oil	OK Not OK Topped Up	Lead Rake1 2nd	Lead Rake2 2nd	Lead Rake3 2nd	Locomotive

	Record time comp car/loco hrs taken		Comp Car	Comp Car	Comp Car	Comp Car	Comp Car	Comp Car	Radiator Water added(mm s/glass)
Rake 1		Engine Oil	Amt Added	Amt Added	Amt Added	Amt Added	Amt Added	Amt Added	Amt Added
Rake 2		Comp Oil	Amt Added	Amt Added	Amt Added	Amt Added	Amt Added	Amt Added	Amt Added
Rake 3		Comp Hrs							Loco Hrs
		Next Service							Cab Cleaned COVID
Locomotive			Running in Auto / Manual Not Running	Running in Auto / Manual Not Running	Running in Auto / Manual Not Running	Running in Auto / Manual Not Running	Running in Auto / Manual Not Running	Running in Auto / Manual Not Running	Loco Km's Travelled
Fuel added to comp cars / Loco			Ltr's	Ltr's	Ltr's	Ltr's	Ltr's	Ltr's	Ltrs

Trip No	Dump Station		Load Station		Delay to Production Yes / No	Delay Time minutes	Rake No	Reason for Delay	Manual Brake Pipe Continuity Completed (Train Drivers Initials Required)
	Arrival Time	Green Light	Arrival Time	Green Light					
1	0340			0515			3	BROKEN RAIL 15.6KM	
2	0550		0525	0658			1		
3	0733		0808	0820			2		
4	0905		0935	1000			3		
5	1035		1110	1127	No		1		
6	1202		1233	1257	No		2		
7	1332		1400	1430	No		3		
8	1505						1		
9									
10									
11									
12									

Time of Fault/Delay	Fault/Delay Description	Notification Raised	Notification No.
	25 KM SPEED RESTRICTION AT 15.6 KM.		

A Continuity Test must be done before moving the Train after Rake changeover!

Document reviewed and necessary Notifications/Maintenance Orders raised. Crewleader Signature.....

Date 5 / 6 / 26 Loco No. R1005 Cab No 2 Facing Andoom Shift Driver/s Molly Rob Glen Day (Night) Shift

The following checks are to be performed at shift handover or close as practical

Vigilance Operational	Engine Oil	Radiator Water	End of Rake Marker Operational	Rake Leakage Check kPa
(Yes) No	(Ok) Not OK Topped up	(OK) Not Ok Topped Up	Rake 1 Y N Rake 2 Y N Rake 3 Y N	Rake 1 Rake 2 ○ Rake 3 ○
Loco Comp Oil	(OK) Not OK Topped Up			

Record time comp car/loco hrs taken			Lead	Rake1	2nd	Lead	Rake2	2nd	Lead	Rake3	2nd	Locomotive
Rake 1		Engine Oil	Comp Car ___ Amt Added	Comp Car ___ Amt Added		Comp Car ___ Amt Added	Comp Car ___ Amt Added		Comp Car ___ Amt Added	Comp Car ___ Amt Added		Radiator Water added(mm s/glass) Amt Added
Rake 2		Comp Oil	Amt Added	Amt Added		Amt Added	Amt Added		Amt Added	Amt Added		Amt Added
Rake 3		Comp Hrs										Loco Hrs 24700
		Next Service										Cab Cleaned COVID
Locomotive	2045		Running in Auto / Manual Not Running	Running in Auto / Manual Not Running		Running in Auto / Manual Not Running	Running in Auto / Manual Not Running		Running in Auto / Manual Not Running	Running in Auto / Manual Not Running		Loco Km's Travelled 496895
Fuel added to comp cars / Loco			Ltr's	Ltr's		Ltr's	Ltr's		Ltr's	Ltr's		4551 Ltrs

Trip No	Dump Station Arrival Time	Dump Station Green Light	Load Station Arrival Time	Load Station Green Light	Delay to Production Yes / No	Delay Time minutes	Rake No	Reason for Delay	Manual Brake Pipe Continuity Completed (Train Drivers Initials Required)
1	1505		1620			1			
2	1650		1730		NO	2		MC	M.M. RR
3	1840		1920		NO	3		MC	M.M. G.M
4	2010		2043	2101		1		MC	M.M. G.M.
5	2138		2210	2230		2			
6	2307		2339	0006		3			
7	0037		0110	0128		1		1500L fuel	
8	0203		0239	0300		2			
9	0335							3051 fuel.	
10									
11									
12									

Time of Fault/Delay	Fault/Delay Description	Notification Raised	Notification No.
	25 KM Speed restriction At 15.6 KM.		

A Continuity Test must be done before moving the Train after Rake changeover!

Document reviewed and necessary Notifications/Maintenance Orders raised. Crewleader Signature.....