Date 9/6/26 Loco No. R1005 Cab No 2 Facing Andoom Shift Driver/s TRUDI / GARY Day (Night) Shift

The following checks are to be performed at shift handover or close as practical

Vigilance Operational	Engine Oil	Radiator Water		End of Rake Marker Operational	Rake Leakage Check kPa
(Yes) No	(Ok) Not OK Topped up ✓	✓ OK Not Ok Topped Up		Rake 1 Y N Rake 2 Y N Rake 3 (Y) N	Rake 1 0 Rake 2 0 Rake 3 0

Loco Comp Oil		Lead	Rake1	2nd	Lead	Rake2	2nd	Lead	Rake3	2nd	Locomotive
(OK) Not OK Topped Up											
Record time comp car/loco hrs taken		Comp Car	Comp Car		Comp Car	Comp Car		Comp Car	Comp Car		Radiator Water added(mm s/glass)
Rake 1	Engine Oil	Amt Added	Amt Added		Amt Added	Amt Added		Amt Added	Amt Added		Amt Added
Rake 2	Comp Oil	Amt Added	Amt Added		Amt Added	Amt Added		Amt Added	Amt Added		Amt Added
Rake 3	Comp Hrs										Loco Hrs 24792
	Next Service										Cab Cleaned COVID
Locomotive 1530		Running in Auto / Manual Not Running	Running in Auto / Manual Not Running		Running in Auto / Manual Not Running	Running in Auto / Manual Not Running		Running in Auto / Manual Not Running	Running in Auto / Manual Not Running		Loco Km's Travelled 499052
Fuel added to comp cars / Loco		Ltr's	Ltr's		Ltr's	Ltr's		Ltr's	Ltr's		2020 Ltrs

Trip No	Dump Station Arrival Time	Dump Station Green Light	Load Station Arrival Time	Load Station Green Light	Delay to Production Yes / No	Delay Time minutes	Rake No	Reason for Delay	Manual Brake Pipe Continuity Completed (Train Drivers Initials Required)
1	1509		1609	1648	NO		2		PH ~~GH~~
2	1721		1752	1812	NO		3		~~GH~~ 2
3	1845		1913	1938	NO		1		~~GH~~ 2
4	2011		2043	2104	NO		2		
5	2137		2209	2237	NO		3		
6	2310		2355	0016	NO		1		
7	0050		0120	0203	NO		2		
8	0237		0330	0354	NO		3		
9	0428						1		
10									
11									
12									

Time of Fault/Delay	Fault/Delay Description	Notification Raised	Notification No.

A Continuity Test must be done before moving the Train after Rake changeover!

Document reviewed and necessary Notifications/Maintenance Orders raised. Crewleader Signature.....