Date 9.8.26 Loco No. R1007 Cab No 2 Facing Andoom Shift Driver/s Glen - Rob (Day) Night Shift

**The following checks are to be performed at shift handover or close as practical**

| Vigilance Operational | Engine Oil | Radiator Water | End of Rake Marker Operational | Rake Leakage Check kPa |
|---|---|---|---|---|
| (Yes) No | (OK) Not OK Topped up | (OK) Not Ok Topped Up | Rake 1 (Y) N Rake 2 (Y) N Rake 3 (Y) N | Rake 1 0 Rake 2 0 Rake 3 0 |

| Loco Comp Oil | Lead | Rake1 | 2nd | Lead | Rake2 | 2nd | Lead | Rake3 | 2nd | Locomotive |
|---|---|---|---|---|---|---|---|---|---|---|
| (OK) Not OK Topped Up | Comp Car I | Comp Car N | | Comp Car O | Comp Car K | | Comp Car J | Comp Car M | | Radiator Water added(mm s/glass) |
| Record time comp car/loco hrs taken | Amt Added | Amt Added | | Amt Added | Amt Added | | Amt Added | Amt Added | | Amt Added |
| Rake 1 0650 | Amt Added | Amt Added | | Amt Added | Amt Added | | Amt Added | Amt Added | | Amt Added |
| Rake 2 0825 | Comp Hrs 11425 | 36052 | | 33498 | 888 | | 16768 | 18560 | | Loco Hrs 329 |
| Rake 3 0525 | Next Service 12000 | 36800 | | 34500 | 9100 | | 17500 | 19000 | | Cab Cleaned COVID |
| Locomotive 0835 | Running In Auto / Manual Not Running | Running In Auto / Manual Not Running | | Running In Auto / Manual Not Running | Running In Auto / Manual Not Running RA | | Running In Auto / Manual Not Running | Running In Auto / Manual Not Running | | Loco Km's Travelled 519954 |
| Fuel added to comp cars // Loco | Ltr's | Ltr's | | Ltr's | Ltr's | | Ltr's | Ltr's | | Ltrs |

| Trip No | Dump Station Arrival Time | Dump Station Green Light | Load Station Arrival Time | Load Station Green Light | Delay to Production Yes / No | Delay Time minutes | Rake No | Reason for Delay | Manual Brake Pipe Continuity Completed (Train Drivers Initials Required) |
|---|---|---|---|---|---|---|---|---|---|
| 1 | 0322 | 0335 | 0400 | 0447 | | | 2 | | |
| 2 | 0522 | | 0600 | 0615 | | | 3 | | Mc RR |
| 3 | 0650 | | 0720 | 0742 | | | 1 | | Mc RR |
| 4 | 0817-0830 | 0855 | | 0910 | | | 2 | Topped up Governor Oil - 16l 4Ltrs. | Mc RR |
| 5 | 0945 | 1000 | 1025 | 1032 | | | 3 | Full-od Cocs | |
| 6 | 1107 | | 1140 | 1153 | | | 1 | | |
| 7 | 1229 | | 1301 | 1313 | | | 2 | | |
| 8 | 1349 | | 1421 | 1437 | | | 3 | | |
| 9 | 1513 | | 1545 | 1602 | | | 1 | | |
| 10 | 1638 | | | | | | 2 | | |
| 11 | | | | | | | | | |
| 12 | | | | | | | | | |

| Time of Fault/Delay | Fault/Delay Description | Notification Raised | Notification No. |
|---|---|---|---|
| | | | |
| | | | |
| | | | |

**A Continuity Test must be done before moving the Train after Rake changeover!**

***Document reviewed and necessary Notifications/Maintenance Orders raised. Crewleader Signature.....***