Date 09/09/26 Loco No. R1007 Cab No 2 Facing Andoom Shift Driver/s TRUDI / [redacted] Day Night Shift

Ensure the following checks are to be performed at shift handover or close as practical

Vigilance Operational	Engine Oil	Radiator Water	End of Rake Marker Operational	Rake Leakage Check kPa
(Yes) No	(OK) Not OK Topped up	(OK) Not Ok Topped Up	Rake 1 (Y) N Rake 2 (Y) N Rake 3 (Y) N	Rake 1 0 Rake 2 0 Rake 3 0
Loco Comp Oil ?	OK Not OK Topped Up			

Record time comp car/loco hrs taken			Lead	Rake1	2nd	Lead	Rake2	2nd	Lead	Rake3	2nd	Locomotive
			Comp Car P	Comp Car J		Comp Car O	Comp Car K		Comp Car E	Comp Car M		Radiator Water added(mm s/glass)
Rake 1	0412	Engine Oil	Amt Added —	Amt Added —		Amt Added	Amt Added		Amt Added 15 PUMPS	Amt Added —		Amt Added
Rake 2	0501	Comp Oil	Amt Added	Amt Added		Amt Added	Amt Added		Amt Added	Amt Added		Amt Added
Rake 3	0712	Comp Hrs	17340	17019		33787	8615		11528	18832		Loco Hrs
		Next Service	18137	17500		34800	9100		12000	19000		Cab Cleaned COVID
Locomotive	0410		Running In Auto / Manual Not Running	Running In Auto / Manual (Not Running)		(Running In Auto) / Manual Not Running	Running In Auto / Manual Not Running		Running In Auto / Manual (Not Running)	Running In Auto / Manual Not Running		Loco Km's Travelled 529809
Fuel added to comp cars / Loco			87 Ltr's	82 Ltr's		Ltr's	Ltr's		132 Ltr's	202 Ltr's		1500 + 910 Ltrs

Trip No	Dump Station Arrival Time	Dump Station Green Light	Load Station Arrival Time	Load Station Green Light	Delay to Production Yes / No	Delay Time minutes	Rake No	Reason for Delay	Manual Brake Pipe Continuity Completed (Train Drivers Initials Required)
1	0325		0408	0422	NO		1	R3 manual load. Didn't fire up	
2	0456		0533	0552	NO		2	R3 had to cycle buttons +++ at dump end	
3	0626		0700	0722	NO		3		R + DT
4	0756		0833	0856	NO		1		2 "
5	0930		1000	1037	NO		2		3 "
6	1111		1302	14-18	NO		3	Training 11-1130 Andoom	
7	1445						1	fuel loco 1500L	
8							2	R3 ccas oil + fuel ✓	
9								R1 ccas oil + fuel ✓	
10								fuel loco 910L	
11									
12									

Time of Fault/Delay	Fault/Delay Description	Notification Raised	Notification No.

A Continuity Test must be done before moving the Train after Rake changeover!

Document reviewed and necessary Notifications/Maintenance Orders raised. Crewleader Signature.....