Date 9/10/26 Loco No. R1005 Cab No 2 Facing Andoom Shift Driver/s Nev - Adam (Day) Night Shift

**The following checks are to be performed at shift handover or close as practical**

| Vigilance Operational | Engine Oil | Radiator Water | End of Rake Marker Operational | Rake Leakage Check kPa |
|---|---|---|---|---|
| (Yes) No | (Ok) Not OK Topped up V90 | (OK) Not Ok Topped Up | Rake 1 (Y) N Rake 2 (Y) N Rake 3 (Y) N | Rake 1 0 Rake 2 0 Rake 3 0 |
| Loco Comp Oil | (OK) Not OK Topped Up | | | |

| | Record time comp car/loco hrs taken | | Lead | Rake1 | 2nd | Lead | Rake2 | 2nd | Lead | Rake3 | 2nd | Locomotive |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | Rake 1 | 0350 | Comp Car P | Comp Car J | | Comp Car O | Comp Car K | | Comp Car I | Comp Car L | | Radiator Water added(mm s/glass) |
| | Rake 2 | 0450 | Engine Oil Amt Added | Amt Added | | Amt Added | Amt Added | | Amt Added | Amt Added | | Amt Added |
| | Rake 3 | 0610 | Comp Oil Amt Added | Amt Added | | Amt Added | Amt Added | | Amt Added | Amt Added | | Amt Added |
| | | | Comp Hrs 17555 | 17303 | | 34017 | 8858 | | 11736 | 74 | | Loco Hrs 26245 |
| | | | Next Service 19137 | 17500 | | 34500 | 9100 | | 12000 | 1001 | | Cab Cleaned COVID |
| | Locomotive | 0745 | (Running in Auto / Manual Not Running) | (Running in Auto / Manual Not Running) | | (Running in Auto / Manual Not Running) | (Running in Auto / Manual Not Running) | | (Running in Auto / Manual Not Running) | (Running in Auto / Manual Not Running) | | Loco Km's Travelled 532818 |
| | Fuel added to comp cars / Loco | | Ltr's | Ltr's | | Ltr's | Ltr's | | Ltr's | Ltr's | | Ltrs |

| Trip No | Dump Station Arrival Time | Dump Station Green Light | Load Station Arrival Time | Load Station Green Light | Delay to Production Yes / No | Delay Time minutes | Rake No | Reason for Delay | Manual Brake Pipe Continuity Completed (Train Drivers Initials Required) |
|---|---|---|---|---|---|---|---|---|---|
| 1 | 0440 | | 0511 | 0530 | N | | 1 | | |
| 2 | 0605 | | 0648 | 0658 | N | | 2 | | ✓ |
| 3 | 0733 | | 0813 | 0824 | N | | 3 | | ✓ |
| 4 | 0900 | | 0942 | 0947 | N | | 1 | | ✓ RM |
| 5 | 1022 | | 1100 | 1106 | N | | 2 | | |
| 6 | 1141 | | 1214 | 1342 | N | | 3 | Power issue Andoom | |
| 7 | 1417 | | 1455 | 1501 | N | | 1 | | |
| 8 | 1536 | | | | | | 2 | | |
| 9 | | | | | | | 3 | | |
| 10 | | | | | | | | | |
| 11 | | | | | | | | | |
| 12 | | | | | | | | | |

| Time of Fault/Delay | Fault/Delay Description | Notification Raised | Notification No. |
|---|---|---|---|
| | 6.6km 40km/h Broker rail | | |
| | Comp car L issue starting perhaps buton | | |
| | | | |

**A Continuity Test must be done before moving the Train after Rake changeover!**

*Document reviewed and necessary Notifications/Maintenance Orders raised. Crewleader Signature.....*