Date 1/4/26 Loco No. 7 Cab No 1 Facing Andoom Shift Driver/s Rob / Colen Day (Night) Shift

The following checks are to be performed at shift handover or close as practical

Vigilance Operational	Engine Oil	Radiator Water	End of Rake Marker Operational	Rake Leakage Check kPa
(Yes) No	(Ok) Not OK Topped up	(OK) Not Ok Topped Up	Rake 1 Y N Rake 2 Y N Rake 3 Y N	Rake 1 Rake 2 Rake 3
Loco Comp Oil	(OK) Not OK Topped Up			

	Lead	Rake1	2nd	Lead	Rake2	2nd	Lead	Rake3	2nd	Locomotive
Record time comp car/loco hrs taken	Comp Car	Comp Car		Comp Car	Comp Car		Comp Car	Comp Car		Radiator Water added(mm s/gless)
Rake 1	Engine Oil: Amt Added	Amt Added		Amt Added	Amt Added		Amt Added	Amt Added		Amt Added
Rake 2	Comp Oil: Amt Added	Amt Added		Amt Added	Amt Added		Amt Added	Amt Added		Amt Added
Rake 3	Comp Hrs									Loco Hrs
	Next Service									Cab Cleaned COVID
Locomotive 17:21	Running in Auto / Manual Not Running	Running in Auto / Manual Not Running		Running in Auto / Manual Not Running	Running in Auto / Manual Not Running		Running in Auto / Manual Not Running	Running in Auto / Manual Not Running		Loco Km's Travelled
Fuel added to comp cars / Loco	Ltr's	Ltr's		Ltr's	Ltr's		Ltr's	Ltr's		3700 Ltrs

Trip No	Dump Station Arrival Time	Dump Station Green Light	Load Station Arrival Time	Load Station Green Light	Delay to Production Yes / No	Delay Time minutes	Rake No	Reason for Delay	Manual Brake Pipe Continuity Completed (Train Drivers Initials Required)
1	1615	1647	1720	1741			2	MC R2	RR
2	1817	1858	1933	1948			3	MC R3	RR
3	2024		2100	2209			1	MC R1	RR
4	2245		2315	0040			2		
5	0115	0140	0210	0246			3	fuelled loco 3700Lts	
6	0321						1		
7							2		
8									
9									
10									
11									
12									

Time of Fault/Delay	Fault/Delay Description	Notification Raised	Notification No.
	Shut down Comp 1 R3 Air leak on compressor		
	Started M		
	R1 No transit light on EOR.		

A Continuity Test must be done before moving the Train after Rake changeover!

Document reviewed and necessary Notifications/Maintenance Orders raised. Crewleader Signature.....

Date 1/4/26 Loco No. R1007 Cab No 1 Facing Andoom Shift Driver/s Steve Jed Pete Day Night Shift

The following checks are to be performed at shift handover or close as practical

Vigilance Operational	Engine Oil	Radiator Water	End of Rake Marker Operational	Rake Leakage Check kPa
(Yes) No	(Ok) Not OK Topped up	(OK) Not Ok Topped Up	Rake 1 Y N Rake 2 Y N Rake 3 Y N	Rake 1 Rake 2 Rake 3
Loco Comp Oil	OK Not OK Topped Up			

	Lead	Rake1	2nd	Lead	Rake2	2nd	Lead	Rake3	2nd	Locomotive
Record time comp car/loco hrs taken	Comp Car JNR	Comp Car KRA		Comp Car R20111	Comp Car NRA		Comp Car RA	Comp Car MNR		Radiator Water added(mm s/glass)
Rake 1	Amt Added 15263	Amt Added 7705		Amt Added 32817	Amt Added 35290		Amt Added 10545	Amt Added 17669		Amt Added
Rake 2	Amt Added 16500	Amt Added 8100		Amt Added 33500	Amt Added		Amt Added 11000	Amt Added 18137		Amt Added
Rake 3										Loco Hrs
										Cab Cleaned COVID
Locomotive R1007	Running in Auto / Manual (Not Running)	Running in Auto / Manual (Not Running)		Running in Auto / Manual (Not Running)	Running in Auto / Manual Not Running		(Running In Auto) / Manual Not Running	Running in Auto / Manual (Not Running)		Loco Km's Travelled
Fuel added to comp cars / Loco	Ltr's	Ltr's		Ltr's	Ltr's		Ltr's	Ltr's		Ltrs

Trip No	Dump Station		Load Station		Delay to Production Yes / No	Delay Time minutes	Rake No	Reason for Delay	Manual Brake Pipe Continuity Completed (Train Drivers Initials Required)
	Arrival Time	Green Light	Arrival Time	Green Light					
1	0341		0417	0510	No		2		SJ
2	0545		0625	0715	No		3		JH
3	0750		0825	0925	No		1		PB
4	1000		1035	1340	NO		2		
5	1415		1450	1540	NO		3		
6	1615						1		
7									
8									
9									
10									
11									
12									

Time of Fault/Delay	Fault/Delay Description	Notification Raised	Notification No.

A Continuity Test must be done before moving the Train after Rake changeover!

Document reviewed and necessary Notifications/Maintenance Orders raised. Crewleader Signature.....