Date 27/10/26 Loco No. R1005 Cab No 2 Facing Andoom Shift Driver/s TROY T GARY Day (Night) Shift

The following checks are to be performed at shift handover or close as practical

Vigilance Operational	Engine Oil ↓ 100 G	Radiator Water	End of Rake Marker Operational	Rake Leakage Check kPa
(Yes) No	(OK) Not OK Topped up	(OK) Not Ok Topped Up	Rake 1 (Y) N Rake 2 (Y) N Rake 3 (Y) N	Rake 1 0 Rake 2 0 Rake 3 1

Loco Comp Oil	Lead	Rake1	2nd	Lead	Rake2	2nd	Lead	Rake3	2nd	Locomotive
(OK) Not OK Topped Up	Comp Car	Comp Car		Comp Car	Comp Car		Comp Car	Comp Car		Radiator Water added(mm s/glass)
Record time comp car/loco hrs taken	Amt Added	Amt Added		Amt Added	Amt Added		Amt Added	Amt Added		Amt Added
Rake 1 / Engine Oil	Amt Added	Amt Added		Amt Added	Amt Added		Amt Added	Amt Added		Amt Added
Rake 2 / Comp Oil										Loco Hrs
Rake 3 / Comp Hrs										Cab Cleaned COVID
Next Service	Running in Auto / Manual Not Running	Running in Auto / Manual Not Running		Running in Auto / Manual Not Running	Running in Auto / Manual Not Running		Running in Auto / Manual Not Running	Running in Auto / Manual Not Running		Loco Km's Travelled 539429
Locomotive 1621	Ltr's	Ltr's		Ltr's	Ltr's		Ltr's	Ltr's		7002 Ltrs
Fuel added to comp cars / Loco										

Trip No	Dump Station Arrival Time	Dump Station Green Light	Load Station Arrival Time	Load Station Green Light	Delay to Production Yes / No	Delay Time minutes	Rake No	Reason for Delay	Manual Brake Pipe Continuity Completed (Train Drivers Initials Required)
1	1525		1600	1630	NO		2	Air bubble hose bag R1 LP end wagon	
2	1704		1735	1809	NO		3	wshop check R3. (replaced)	R GH
3	1839		0911	1945	NO		1	R3 telemetry frozen/displaying transit/no reading	R GH
4	2014		2045	2107	NO		2	no lights EOR - needed manual	R GH
5	2141		2215	2345	NO		3	R3 m/c required LP + Andoom, dump	
6	2306		2339	2351	NO				
7	0027		0058	0111	NO				
8	0144		0230	0231	NO			Fuel loco	
9	0304		0340	0354	NO				
10	0427								
11									
12									

Time of Fault/Delay	Fault/Delay Description	Notification Raised	Notification No.
1804	R2 m/c Andoom no reading telemetry. came good on changing ends Andoom		
Shift:	R3 m/c LP + Andoom. EOR NO power		

A Continuity Test must be done before moving the Train after Rake changeover!

Document reviewed and necessary Notifications/Maintenance Orders raised. Crewleader Signature.....