Date 28/4/21 Loco No. R1007 Cab No 2 Facing Andoom Shift Driver/s Neil Adams (Day) Night Shift

The following checks are to be performed at shift handover or close as practical

Vigilance Operational	Engine Oil	Radiator Water		End of Rake Marker Operational			Rake Leakage Check kPa		
(Yes) No	(Ok) Not OK Topped up	(OK) Not Ok Topped Up		Rake 1 Y N	Rake 2 Y N	Rake 3 Y N	Rake 1	Rake 2	Rake 3
Loco Comp Oil ?	(OK) Not OK Topped Up	Lead	Rake1 2nd	Lead	Rake2 2nd	Lead 1	Rake3 M 2nd	Locomotive	

Record time comp car/loco hrs taken

			Comp Car J	Comp Car O	Comp Car P	Comp Car N	Comp Car 1	Comp Car M	Radiator Water added(mm s/glass)
Rake 1	0415	Engine Oil	Amt Added 554	Amt Added	Amt Added 904	Amt Added 487	Amt Added 247	Amt Added 239	Amt Added
Rake 2	0610	Comp Oil	Amt Added	Amt Added	Amt Added	Amt Added	Amt Added	Amt Added	Amt Added
Rake 3	0750	Comp Hrs	15946	37901	16153	35565	10753	17898	Loco Hrs
		Next Service	16500	33500	17057	36052	11000	18137	Cab Cleaned COVID
Locomotive	0530		Running in Auto / Manual (Not Running)	Running in Auto / Manual (Not Running)	Running in Auto / Manual (Not Running)	Running in Auto / Manual (Not Running)	Running in Auto / Manual (Not Running)	Running in Auto / Manual (Not Running)	Loco Km's Travelled 495182
Fuel added to comp cars / Loco			Ltr's	Ltr's	Ltr's	Ltr's	Ltr's	Ltr's	2400, 1053 ltrs

Trip No	Dump Station Arrival Time	Dump Station Green Light	Load Station Arrival Time	Load Station Green Light	Delay to Production Yes / No	Delay Time minutes	Rake No	Reason for Delay	Manual Brake Pipe Continuity Completed (Train Drivers Initials Required)
1	0422		0518	0632	N		1	fuel loco M/C	
2	0708		0756	0844	N		2		
3	0921		1035	1125	N		3		
4	1200		1237	1345	N		1		
5	1420						2	FUEL 1053L	
6									
7									
8									
9									
10									
11									
12									

Time of Fault/Delay	Fault/Delay Description	Notification Raised	Notification No.

A Continuity Test must be done before moving the Train after Rake changeover!

Document reviewed and necessary Notifications/Maintenance Orders raised. Crewleader Signature.....

Date 28/4/26 Loco No. 8007 Cab No 2 Facing Andoom Shift Driver/s ROB-GLEN. Day (Night) Shift

The following checks are to be performed at shift handover or as close as practical

Vigilance Operational	Engine Oil	Radiator Water	End of Rake Marker Operational	Rake Leakage Check kPa
(Yes) No	(Ok) Not OK Topped up	(OK) Not Ok Topped Up	Rake 1 Y N Rake 2 Y N Rake 3 Y N	Rake 1 Rake 2 Rake 3
Loco Comp Oil	(OK) Not OK Topped Up			

Record time comp car/loco hrs taken		Lead	Rake1	2nd	Lead	Rake2	2nd	Lead	Rake3	2nd	Locomotive
Rake 1		Engine Oil	Comp Car Amt Added	Comp Car Amt Added	Comp Car Amt Added	Comp Car Amt Added		Comp Car Amt Added	Comp Car Amt Added		Radiator Water added(mm s/glass) Amt Added
Rake 2		Comp Oil	Amt Added	Amt Added	Amt Added	Amt Added		Amt Added	Amt Added		Amt Added
Rake 3		Comp Hrs									Loco Hrs
		Next Service									Cab Cleaned COVID
Locomotive	16443		Running In Auto / Manual Not Running	Running In Auto / Manual Not Running	Running In Auto / Manual Not Running	Running In Auto / Manual Not Running		Running In Auto / Manual Not Running	Running In Auto / Manual Not Running		Loco Km's Travelled 495384
Fuel added to comp cars / loco?			Ltr's	Ltr's	Ltr's	Ltr's		Ltr's	Ltr's		1350 Ltrs

Trip No	Dump Station Arrival Time	Dump Station Green Light	Load Station Arrival Time	Load Station Green Light	Delay to Production Yes / No	Delay Time minutes	Rake No	Reason for Delay	Manual Brake Pipe Continuity Completed (Train Drivers Initials Required)
1	1420		1545	1558	N		2		
2	1633		1708	1808			3		
3	1844		1920	2016			1	MCR3	RR.
4	2052		2126	2219			2	MCR1	RR.
5	2255		2325	0017			3	MCR2	RR
6	0052		0120	0212			1		
7	0247	0315	0345	0410			2	Andoom Slow	
8	0445						3	loco fuelled 1350 Ltrs	
9									
10									
11									
12									

Time of Fault/Delay	Fault/Delay Description	Notification Raised	Notification No.

A Continuity Test must be done before moving the Train after Rake changeover!

Document reviewed and necessary Notifications/Maintenance Orders raised. Crewleader Signature.....