Date 28/8/26 Loco No. R1007 Cab No 2 Facing Andoom Shift Driver/s [redacted] JED Steve (Day) Night Shift

The following checks are to be performed at shift handover or close as practical

Vigilance Operational	Engine Oil	Radiator Water	End of Rake Marker Operational	Rake Leakage Check kPa
(Yes) No	(Ok) Not OK Topped up	OK Not Ok Topped Up	Rake 1 Y N Rake 2 Y N Rake 3 Y N	Rake 1 Rake 2 Rake 3

Loco Comp Oil	OK Not OK Topped Up	Lead	Rake1	2nd	Lead	Rake2	2nd	Lead	Rake3	2nd	Locomotive
	Record time comp car/loco hrs taken	Comp Car	Comp Car		Comp Car O	Comp Car K		Comp Car J	Comp Car M		Radiator Water added(mm s/glass)
Rake 1		Amt Added	Amt Added	Engine Oil	Amt Added	Amt Added		Amt Added	Amt Added		Amt Added
Rake 2	09:19	Amt Added	Amt Added	Comp Oil	Amt Added	Amt Added		Amt Added	Amt Added		Amt Added
Rake 3	06:24			Comp Hrs	33650	8555		16906	18738		Loco Hrs
				Next Service	34500	9100		17500	19000		Cab Cleaned COVID
Locomotive	09:40	Running in Auto / Manual Not Running	Running in Auto / Manual Not Running		Running in Auto / Manual Not Running	Running in Auto / Manual (Not Running)		Running in Auto / Manual Not Running	Running in Auto / Manual (Not Running)		Loco Km's Travelled 525 133
Fuel added to comp cars / Loco		Ltr's	Ltr's		Ltr's	Ltr's		Ltr's	Ltr's		1600 Ltrs

Trip No	Dump Station Arrival Time	Dump Station Green Light	Load Station Arrival Time	Load Station Green Light	Delay to Production Yes / No	Delay Time minutes	Rake No	Reason for Delay	Manual Brake Pipe Continuity Completed (Train Drivers Initials Required)
1	0332		0413	0425			1		[redacted]
2	0500		0532	0553			2		[redacted]
3	0628		0702	0720			3		[redacted]
4	0755		0827	0848			1		[redacted]
5	0923		1005	1013			2	REFUEL - 1600L	
6	1048		1121	1137	No		3		
7	1212			1503	Yes		1	EW Down.	
8	1538						2		
9							3		
10									
11									
12									

Time of Fault/Delay	Fault/Delay Description	Notification Raised	Notification No.

A Continuity Test must be done before moving the Train after Rake changeover!

Document reviewed and necessary Notifications/Maintenance Orders raised. Crewleader Signature.....

Date 28/8/26 Loco No. R1005 Cab No 2 Facing Andoom Shift Driver/s Rob Glen (Day) (Night) Shift

The following checks are to be performed at shift handover or close as practical

Vigilance Operational	Engine Oil	Radiator Water	End of Rake Marker Operational	Rake Leakage Check kPa
(Yes) No	(Ok) Not OK Topped up	(OK) Not Ok Topped Up	Rake 1 Y N Rake 2 Y N Rake 3 Y N	Rake 1 Rake 2 Rake 3
Loco Comp Oil	(OK) Not OK Topped Up			

	Lead	Rake1	2nd	Lead	Rake2	2nd	Lead	Rake3	2nd	Locomotive
Record time comp car/loco hrs taken	Comp Car	Comp Car		Comp Car	Comp Car		Comp Car	Comp Car		Radiator Water added(mm s/glass)
Rake 1	Amt Added	Amt Added		Amt Added	Amt Added		Amt Added	Amt Added		Amt Added
Rake 2	Amt Added	Amt Added		Amt Added	Amt Added		Amt Added	Amt Added		Amt Added
Rake 3										Loco Hrs -
										Cab Cleaned COVID
Locomotive 1557	Running in Auto / Manual Not Running	Running in Auto / Manual Not Running		Running in Auto / Manual Not Running	Running in Auto / Manual Not Running		Running in Auto / Manual Not Running	Running in Auto / Manual Not Running		Loco Km's Travelled 525256
Fuel added to comp cars / Loco	Ltr's	Ltr's		Ltr's	Ltr's		Ltr's	Ltr's		1000 Ltrs

Trip No	Dump Station		Load Station		Delay to Production Yes / No	Delay Time minutes	Rake No	Reason for Delay	Manual Brake Pipe Continuity Completed (Train Drivers Initials Required)
	Arrival Time	Green Light	Arrival Time	Green Light					
1	1538		1620	1627			2	MC R2	RL
2	1703		1737	1741			3	MC R3	RL GM
3	1817	1820	1853	1910			1	MC R1	RL GM
4	1946		2018	2045			2		
5	2121		2154	2216			3		
6	2252		2325	2345			1		
7	0020		0050	0106			2		
8	0141	0155	0220	0243			3	Fuelled Loco 1000 Ltrs	
9	0318		0358	0407			1		
10	0442						2		
11									
12									

Time of Fault/Delay	Fault/Delay Description	Notification Raised	Notification No.

A Continuity Test must be done before moving the Train after Rake changeover!

Document reviewed and necessary Notifications/Maintenance Orders raised. Crewleader Signature.....