Date 28/1/26 Loco No. R1005 Cab No 1 Facing Andoom Shift Driver/s ADAM TRUDY (Day) Night Shift

The following checks are to be performed at shift handover or close as practical

Vigilance Operational	Engine Oil	Radiator Water	End of Rake Marker Operational	Rake Leakage Check kPa
(Yes) No	(Ok) Not OK Topped up	(OK) Not Ok Topped Up	Rake 1 (Y) N Rake 2 (Y) N Rake 3 (Y) N	Rake 1 0 Rake 2 0 Rake 3 1
Loco Comp Oil	(OK) Not OK Topped Up			

	Record time comp car/loco hrs taken		Lead	Rake1	2nd	Lead	Rake2	2nd	Lead	Rake3	2nd	Locomotive
Rake 1	0353	Engine Oil	Comp Car N Amt Added 20 pumps	Comp Car J Amt Added *		Comp Car P Amt Added 30 pumps	Comp Car O Amt Added OK		Comp Car K Amt Added 20 pumps	Comp Car M Amt Added 20 pumps		Radiator Water added(mm s/glass) Amt Added
Rake 2	0607	Comp Oil	Amt Added	Amt Added		Amt Added	Amt Added		Amt Added	Amt Added		Amt Added
Rake 3	0806	Comp Hrs	34967	15496		15402	32753		7156	17318		Loco Hrs 22448
		Next Service	35000	15 500		16000	33500		7001	18137		Cab Cleaned COVID
Locomotive	0505		Running in Auto / Manual Not Running	Running in Auto / Manual Not Running		Running in Auto / Manual Not Running	Running in Auto / Manual Not Running		Running in Auto / Manual Not Running	Running in Auto / Manual Not Running		Loco Km's Travelled 459747
Fuel added to comp cars / Loco			50 Ltr's	160 Ltr's		220 Ltr's	Ltr's		58 Ltr's	152 Ltr's		2700 Ltrs

Trip No	Dump Station Arrival Time	Dump Station Green Light	Load Station Arrival Time	Load Station Green Light	Delay to Production Yes / No	Delay Time minutes	Rake No	Reason for Delay	Manual Brake Pipe Continuity Completed (Train Drivers Initials Required)
1	0427		0504	0543	N		1	J → N cc swapped	
2	0617		0658	0736	N		2	cc not swapped. O tagged (as backup only) fuel oils	JP
3	0810		0901	0927	N		3	M → K cc swapped, fuel x 2 + oils	JP
4	1001		1135	1135	X		1	Broken Rail 2.1 Km	JP
5	1210		1250	1331			2		
6	1406						3	FUEL 2700L	
7	1554						1		
8									
9									
10									
11									
12									

Time of Fault/Delay	Fault/Delay Description	Notification Raised	Notification No.
0708	Rod over white (21) points good. Track maintenance aware.		
0815	cc K over hours		
1040	Broken rail approx 2.1 Km no speed restriction, plated		

A Continuity Test must be done before moving the Train after Rake changeover!

Document reviewed and necessary Notifications/Maintenance Orders raised. Crewleader Signature.....

Fault/Delay	Fault/Delay Description	Notification Raised	Notification No.