Date 28/01/26 Loco No. RL005 Cab No 1 Facing Andoom Shift Driver/s JED ; Peter Day (Night) Shift

**The following checks are to be performed at shift handover or close as practical**

| Vigilance Operational | Engine Oil | Radiator Water | End of Rake Marker Operational | Rake Leakage Check kPa |
|---|---|---|---|---|
| (Yes) No | (Ok) Not OK Topped up | (OK) Not Ok Topped Up | Rake 1 (Y) N Rake 2 (Y) N Rake 3 (Y) N | Rake 1 0 Rake 2 0 Rake 3 0 |
| Loco Comp Oil: (OK) Not OK Topped Up | | | | |

| Record time comp car/loco hrs taken | | | Lead Rake1 2nd | | Lead Rake2 2nd | | Lead Rake3 2nd | | Locomotive |
|---|---|---|---|---|---|---|---|---|---|
| Rake 1 | | Engine Oil | Comp Car / Amt Added | Comp Car / Amt Added | Comp Car / Amt Added | Comp Car / Amt Added | Comp Car / Amt Added | Comp Car / Amt Added | Radiator Water added(mm s/glass) |
| Rake 2 | | Comp Oil | Amt Added | Amt Added | Amt Added | Amt Added | Amt Added | Amt Added | Amt Added |
| Rake 3 | | Comp Hrs | | | | | | | Amt Added |
| | | Next Service | | | | | | | Loco Hrs 22462 |
| Locomotive | 1900 | | Running in Auto / Manual Not Running | Running in Auto / Manual Not Running | Running in Auto / Manual Not Running | Running in Auto / Manual Not Running | Running in Auto / Manual Not Running | Running in Auto / Manual Not Running | Cab Cleaned COVID |
| **Fuel added to comp cars / Loco** | | | Ltr's | Ltr's | Ltr's | Ltr's | Ltr's | Ltr's | Loco Km's Travelled 460022 |
| | | | | | | | | | 1500 Ltrs |

| Trip No | Dump Station Arrival Time | Dump Station Green Light | Load Station Arrival Time | Load Station Green Light | Delay to Production Yes / No | Delay Time minutes | Rake No | Reason for Delay | Manual Brake Pipe Continuity Completed (Train Drivers Initials Required) |
|---|---|---|---|---|---|---|---|---|---|
| 1 | 1559 | | 1635 | 1715 | No | | 1 | | |
| 2 | 1750 | | 1825 | 1920 | No | | 2 | | |
| 3 | 1955 | | 2040 | 2110 | No | | 3 | | |
| 4 | 2145 | | 2231 | 2327 | NO | | 1 | LOCO FUEL 1500L | |
| 5 | 0002 | | 0042 | 0103 | NO | | 2 | | |
| 6 | 0138 | | | | | | 3 | | |
| 7 | | | | | | | | | |
| 8 | | | | | | | | | |
| 9 | | | | | | | | | |
| 10 | | | | | | | | | |
| 11 | | | | | | | | | |
| 12 | | | | | | | | | |

| Time of Fault/Delay | Fault/Delay Description | Notification Raised | Notification No. |
|---|---|---|---|
| | | | |
| | | | |
| | | | |

**A Continuity Test must be done before moving the Train after Rake changeover!**

*Document reviewed and necessary Notifications/Maintenance Orders raised. Crewleader Signature.....*

| Fault/Delay | Fault/Delay Description | Notification Raised | Notification No. |
|---|---|---|---|
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |