Date 28 / 6 / 26

Loco No. R1007

Cab No 2 Facing Andoom

Shift Driver/s TROD

Day ~~Night~~ Shift

The following checks are to be performed at shift handover or close as practical

Vigilance Operational [✓ Yes] No

Loco Comp Oil ? OK Not OK Topped Up

Engine Oil [✓ OK] Not OK Topped up

Radiator Water [✓ OK] Not Ok Topped Up

End of Rake Marker Operational: Rake 1 [✓ Y] N | Rake 2 [✓ Y] N | Rake 3 [✓ Y] N

Rake Leakage Check kPa: Rake 1 0 | Rake 2 0 | Rake 3 0

Record time comp car/loco hrs taken	
Rake 1	0415
Rake 2	0710
Rake 3	0839
Locomotive	0539

Fuel added to comp cars / loco

	Rake1 Lead	Rake1 2nd	Rake2 Lead	Rake2 2nd	Rake3 Lead	Rake3 2nd	Locomotive
	Comp Car J	Comp Car O	Comp Car P	Comp Car K	Comp Car N	Comp Car M	
Engine Oil	Amt Added	Amt Added	Amt Added	Amt Added	Amt Added	Amt Added	Radiator Water added(mm s/glass) Amt Added
Comp Oil	Amt Added	Amt Added	Amt Added	Amt Added	Amt Added	Amt Added	Amt Added
Comp Hrs	16450	33288	16710	8209	35778	18237	Loco Hrs
Next Service	16500	33500	17057	9100	36052	19000	Cab Cleaned covid
	Running In Auto / Manual [✓ Not Running]	[✓ Running In Auto] / Manual Not Running	[✓ Running In Auto] / Manual Not Running	Running In Auto / Manual [✓ Not Running]	[✓ Running In Auto] / Manual ~~Not Running~~	Running In Auto / Manual [✓ Not Running]	Loco Km's Travelled 506440
	Ltr's	Ltr's	Ltr's	Ltr's	Ltr's	Ltr's	700 Ltrs

Trip No	Dump Station Arrival Time	Dump Station Green Light	Load Station Arrival Time	Load Station Green Light	Delay to Production Yes / No	Delay Time minutes	Rake No	Reason for Delay	Manual Brake Pipe Continuity Completed (Train Drivers Initials Required)
1	0411		0503	0503	Y		3	dump delays (slow) / op swap	R + SW
2	0537	0539	0610	0633	N		1	slow dumping	R + SW
3	0707		0741	0749	N		2		R + Shop DT
4	0823	0839	0925	0925	Y	35m Partial	3	slow dumping / hang up / wShop inspect	
5	0959		1037	1051	N		1	(+ ran out of ore / wShop / slow dump). R3 CCM	
6	1125		1259	1259	Y		2	RM2 troubles. LP	
7	1333	1402	1445	1447	Y		3	Dump delays / fuel loco (8 mins)	
8	1521						1		
9									
10									
11									
12									

Time of Fault/Delay	Fault/Delay Description	Notification Raised	Notification No.
	Driverside blind in blue cab 2 - cant see in morning sun glare		

A Continuity Test must be done before moving the Train after Rake changeover!

Document reviewed and necessary Notifications/Maintenance Orders raised. *Crewleader Signature*......