Date 14/04/26 Loco No. R1005 Cab No 1 Facing Andoom Shift Driver/s PETE MOLLY Day Night Shift

The following checks are to be performed at shift handover or close as practical

Vigilance Operational	Engine Oil	Radiator Water	End of Rake Marker Operational	Rake Leakage Check kPa
Yes No	Ok Not OK Topped up	OK Not Ok Topped Up	Rake 1 Y N Rake 2 Y N Rake 3 Y N	Rake 1 Rake 2 Rake 3 0
Loco Comp Oil	OK Not OK Topped Up			

	Lead	Rake1	2nd	Lead	Rake2	2nd	Lead	Rake3	2nd	Locomotive
Record time comp car/loco hrs taken	Comp Car J	Comp Car K		Comp Car P	Comp Car N		Comp Car TR3	Comp Car MR3		Radiator Water added(mm s/glass)
Rake 1	Amt Added RA	Amt Added NR		Amt Added NR	Amt Added RA		Amt Added 10638	Amt Added 17287		Amt Added
Rake 2	Amt Added	Amt Added		Amt Added	Amt Added		Amt Added 11000	Amt Added 18137		Amt Added
Rake 3	Comp Hrs 15875	7802		16120	35375		RA	NK		Loco Hrs
	Next Service 16500	8100		17057	36052					Cab Cleaned COVID
Locomotive	Running in Auto / Manual Not Running	Running in Auto / Manual Not Running		Running in Auto / Manual Not Running	Running in Auto / Manual Not Running		Running in Auto / Manual Not Running	Running in Auto / Manual Not Running		Loco Km's Travelled
Fuel added to comp cars / Loco	Ltr's	Ltr's		Ltr's	Ltr's		Ltr's	Ltr's		700 Ltrs

Trip No	Dump Station Arrival Time	Dump Station Green Light	Load Station Arrival Time	Load Station Green Light	Delay to Production Yes / No	Delay Time minutes	Rake No	Reason for Delay	Manual Brake Pipe Continuity Completed (Train Drivers Initials Required)
1	0413		0508	0615			3	M/C	M.M.
2	0650		0740	0746			1	M/C	M.M.
3	0821		1310	1400			2		M.M.
4	1444						3		
5								LOCO FUEL 700L	
6									
7									
8									
9									
10									
11									
12									

Time of Fault/Delay	Fault/Delay Description	Notification Raised	Notification No.

A Continuity Test must be done before moving the Train after Rake changeover!

Document reviewed and necessary Notifications/Maintenance Orders raised. Crewleader Signature.....