Date 14/8/26 Loco No. R1005 Cab No A Facing Andoom Shift Driver/s TRUO: Day (Night) Shift

The following checks are to be performed at shift handover or close as practical

Vigilance Operational	Engine Oil ↓ 50	Radiator Water	End of Rake Marker Operational	Rake Leakage Check kPa
(Yes) No	(Ok) Not OK Topped up	(OK) Not Ok Topped Up	Rake 1 Y N Rake 2 (Y) N Rake 3 (Y) N	Rake 1 0 Rake 2 0 Rake 3 0
Loco Comp Oil	OK Not OK Topped Up			

	Record time comp car/loco hrs taken		Lead	Rake1	2nd	Lead	Rake2	2nd	Lead	Rake3	2nd	Locomotive
Rake 1		Engine Oil	Comp Car Amt Added	Comp Car Amt Added		Comp Car Amt Added	Comp Car Amt Added		Comp Car Amt Added	Comp Car Amt Added		Radiator Water added(mm s/glass) Amt Added
Rake 2		Comp Oil	Amt Added	Amt Added		Amt Added	Amt Added		Amt Added	Amt Added		Amt Added
Rake 3		Comp Hrs										Loco Hrs
		Next Service										Cab Cleaned: COVID
Locomotive	2006		Running In Auto / Manual Not Running	Running In Auto / Manual Not Running		Running In Auto / Manual Not Running	Running In Auto / Manual Not Running		Running In Auto / Manual Not Running	Running In Auto / Manual Not Running		Loco Km's Travelled 518013
Fuel added to comp/car/Loco			Ltr's	Ltr's		Ltr's	Ltr's		Ltr's	Ltr's		1500 Ltrs

Trip No	Dump Station Arrival Time	Dump Station Green Light	Load Station Arrival Time	Load Station Green Light	Delay to Production Yes / No	Delay Time minutes	Rake No	Reason for Delay	Manual Brake Pipe Continuity Completed (Train Drivers Initials Required)
1	1623		1700	1720	NO		1		R
2	1754		1825	1845	NO		2		T
3	1919		2005	2021	NO		3	fuel loco R3 manual load	R + Andoom
4	2055		2126	2145	NO		1		
5	2220		2253	2302	NO		2	2350 - 0030 crew break	
6	2336		0059	0059	Y		3		
7	0138345		0236	0236			1	Max 120 AMPS in N8, sanding light	
8	0325						2	N3 and above. 25-30 km/hr max on loaded	
9							3	Came good momentarily then above occurred again (transition prob?)	
10									
11								Reboot loco Andoom	
12									

Time of Fault/Delay	Fault/Delay Description	Notification Raised	Notification No.

A Continuity Test must be done before moving the Train after Rake changeover!

Document reviewed and necessary Notifications/Maintenance Orders raised. Crewleader Signature.....