Date 15/8/24 Loco No. 1005 Cab No 2 Facing Andoom Shift Driver/s Steve Pete Ted Day Night Shift

The following checks are to be performed at shift handover or close as practical

Vigilance Operational	Engine Oil	Radiator Water	End of Rake Marker Operational	Rake Leakage Check kPa
Yes No	OK Not OK Topped up	OK Not Ok Topped Up	Rake 1 Y N Rake 2 Y N Rake 3 Y N	Rake 1 Rake 2 Rake 3
Loco Comp Oil	OK Not OK Topped Up			

Record time comp car/loco hrs taken		Lead Rake1 2nd	Lead Rake2 2nd	Lead Rake3 2nd	Locomotive
Rake 1	0725	Comp Car J / Comp Car K	Comp Car P / Comp Car N	Comp Car I / Comp Car M	Radiator Water added(mm s/gless)
Rake 2	0636	Amt Added / Amt Added	Amt Added / Amt Added	Amt Added / Amt Added	Amt Added
Rake 3	1149	Comp Hrs 15691 / 7599.	15973 / 35174	10415 / 17637	Loco Hrs 23443
		Next Service 16500 / 8100	16000 / 36000	11000 / 18137	Cab Cleaned (Y/N)
Locomotive	1233	Running In Auto / Manual Not Running / Not Running	Running In Auto / Manual Not Running / Not Running	Running In Auto / Manual Not Running / Not Running	Loco Km's Travelled 477556
Fuel added to comp cars / Loco		Ltr's / Ltr's	Ltr's / Ltr's	Ltr's / Ltr's	Ltrs

Trip No	Dump Station Arrival Time	Dump Station Green Light	Load Station Arrival Time	Load Station Green Light	Delay to Production Yes / No	Delay Time minutes	Rake No	Reason for Delay	Manual Brake Pipe Continuity Completed (Train Drivers Initials Required)
1	0145		0415	0915			1	Andoom Down Mayday in Mine. MC	
2	0950		1024	1120			2		
3	1155		1228	1330	N		3		
4	1405		1510	1518			1		
5	1548						2		
6							3		
7									
8									
9									
10									
11									
12									

Time of Fault/Delay	Fault/Delay Description	Notification Raised	Notification No.

A Continuity Test must be done before moving the Train after Rake changeover!

Document reviewed and necessary Notifications/Maintenance Orders raised. Crewleader Signature.....