Date 15/4/26 Loco No. R1005 Cab No 1 Facing Andoom Shift Driver/s NEV - MOLLY Day Night Shift

The following checks are to be performed at shift handover or close as practical

Vigilance Operational	Engine Oil	Radiator Water	End of Rake Marker Operational	Rake Leakage Check kPa
(Yes) No	(Ok) Not OK Topped up	(OK) Not Ok Topped Up	Rake 1 (Y) N Rake 2 (Y) N Rake 3 (Y) N	Rake 1 0 Rake 2 0 Rake 3
Loco Comp Oil	(OK) Not OK Topped Up			

Record time comp car/loco hrs taken			Lead	Rake1	2nd	Lead	Rake2	2nd	Lead	Rake3	2nd	Locomotive
Rake 1	0350	Engine Oil	Comp Car J	Comp Car K		Comp Car P	Comp Car N		Comp Car I	Comp Car M		Radiator Water added(mm s/glass)
Rake 2	0700	Comp Oil	Amt Added	Amt Added		Amt Added	Amt Added		Amt Added	Amt Added		Amt Added
Rake 3	1030	Comp Hrs	15890	7802		16134	35375		10660	17787		Amt Added
		Next Service	16500	8100		17057	36052		11000	18137		Loco Hrs 23848
Locomotive	0440		Running in Auto / Manual (Not Running)	Running in Auto / Manual (Not Running)		Running in Auto / Manual Not Running	Running in Auto / Manual Not Running		Running in Auto / Manual (Not Running)	Running in Auto / Manual (Not Running)		Cab Cleaned COVID
Fuel added to comp cars / Loco			156 Ltr's	Ltr's		240 Ltr's	Ltr's		198 Ltr's	Ltr's		Loco Km's Travelled 482843 Ltrs

Trip No	Dump Station		Load Station		Delay to Production Yes / No	Delay Time minutes	Rake No	Reason for Delay	Manual Brake Pipe Continuity Completed (Train Drivers Initials Required)
	Arrival Time	Green Light	Arrival Time	Green Light					
1	0426		0515	0655	N		1	Comp K wouldn't Take fuel M/c	M.M.
2	0655		0755	0839	NP		3	M/c	M.M.
3	0915	1012	1058	1138	NO		2	M/c	M.M
4	1213		1342	1420	NO		1	M/c	
5	1450						2	Loco fuel 658L	
6									
7									
8									
9									
10									
11									
12									

Time of Fault/Delay	Fault/Delay Description	Notification Raised	Notification No.

A Continuity Test must be done before moving the Train after Rake changeover!

Document reviewed and necessary Notifications/Maintenance Orders raised. Crewleader Signature.....