Date 18/6/26 Loco No. R1005 Cab No 2 Facing Andoom Shift Driver/s [redacted] TRUDI MOLLY Day Night Shift

The following checks are to be performed at shift handover or close as practical

Vigilance Operational	Engine Oil ↓ 130G	Radiator Water	End of Rake Marker Operational	Rake Leakage Check kPa
(Yes) No	(Ok) Not OK Topped up	(OK) Not Ok Topped Up	Rake 1 (Y) N Rake 2 (Y) N Rake 3 (Y) N	Rake 1 Rake 2 0 Rake 3 0
Loco Comp Oil	(OK) Not OK Topped Up			

Record time comp car/loco hrs taken			Lead	Rake1	2nd	Lead	Rake2	2nd	Lead	Rake3	2nd	Locomotive
			Comp Car J		Comp Car O	Comp Car P		Comp Car K	Comp Car M		Comp Car T	Radiator Water added(mm a/glass)
Rake 1	0727	Engine Oil	Amt Added 25 pumps		Amt Added -	Amt Added (checked 17/6)			Amt Added -		Amt Added 20 pumps	Amt Added
Rake 2	0448	Comp Oil	Amt Added -		Amt Added -	Amt Added		Amt Added	Amt Added		Amt Added -	Amt Added
Rake 3	0529	Comp Hrs	16423		33149	16585		8168	18141		11096	Loco Hrs
		Next Service	16500		33500	17057		9100	19000		11000	Cab Cleaned COVID
Locomotive	0455		Running In Auto / Manual (Not Running)		Running In Auto / Manual Not Running	(Running In Auto / Manual Not Running)		Running In Auto / Manual (Not Running)	Running In Auto / Manual Not Running		Running In Auto / Manual (Not Running)	Loco Km's Travelled 503105
Fuel added to comp cars / loco			130 Ltr's		Ltr's	Ltr's		Ltr's	Ltr's		220 Ltr's	Ltrs

Trip No	Dump Station Arrival Time	Dump Station Green Light	Load Station Arrival Time	Load Station Green Light	Delay to Production Yes / No	Delay Time minutes	Rake No	Reason for Delay	Manual Brake Pipe Continuity Completed (Train Drivers Initials Required)
1	0402		0435	0501	NO		2		R + SW
2	0535		0610	0631	NO		3	EE swapped. Oils checked. Fuel. Driver rake	R
3	0705	0715	0758	0803	NO		1	EE swapped. Oils checked. Fuel. Dump delays changed at andoom	R
4	0837		0910	0931	NO		2		
5	1005		1055	1100	NO		3		
6	1135		1208	1227	NO		1		
7	130		1405		YES		2	loco fuelled 1470L	
8	1443		1547	1580			3		
9								Comp N shunted IN	
10									
11								Comp M shunted at	
12									

Time of Fault/Delay	Fault/Delay Description	Notification Raised	Notification No.
	Oil - need top up over next few days (loco)		
	R3 ccI over hours		

A Continuity Test must be done before moving the Train after Rake changeover!

Document reviewed and necessary Notifications/Maintenance Orders raised. Crewleader Signature.....