Date 18/7/2026 Loco No. R1007 Cab No 2 Facing Andoom Shift Driver/s Nev/Adam (Day) Night Shift

The following checks are to be performed at shift handover or close as practical

Vigilance Operational	Engine Oil	Radiator Water	End of Rake Marker Operational	Rake Leakage Check kPa
(Yes) No	(Ok) Not OK Topped up	(OK) Not Ok Topped Up	Rake 1 (Y) N Rake 2 (Y) N Rake 3 (Y) N	Rake 1 1 Rake 2 0 Rake 3 0

Loco Comp Oil 7	OK	Not OK	Topped Up

Record time comp car/loco hrs taken			Lead	Rake1	2nd	Lead	Rake2	2nd	Lead	Rake3	2nd	Locomotive
			Comp Car I		Comp Car N	Comp Car P		Comp Car K	Comp Car J		Comp Car M	Radiator Water added(mm s/glass)
Rake 1	0720	Engine Oil	Amt Added		Amt Added	Amt Added		Amt Added	Amt Added		Amt Added	Amt Added
Rake 2	0340	Comp Oil	Amt Added		Amt Added	Amt Added		Amt Added	Amt Added		Amt Added	Amt Added
Rake 3	0535	Comp Hrs	11237		35895	16973		8268	16612		18363	Loco Hrs
		Next Service	12000		36800	17057		9100	17500		19000	Cab Cleaned COVID
Locomotive	0650		Running in Auto / Manual Not Running		Running in Auto / Manual Not Running	Running in Auto / Manual Not Running		Running in Auto / Manual Not Running	Running in Auto / Manual Not Running		Running in Auto / Manual Not Running	Loco Km's Travelled 514303.3
Fuel added to comp cars / Loco			Ltr's		Ltr's	Ltr's		Ltr's	Ltr's		Ltr's	Ltrs

Trip No	Dump Station		Load Station		Delay to Production Yes / No	Delay Time minutes	Rake No	Reason for Delay	Manual Brake Pipe Continuity Completed (Train Drivers Initials Required)
	Arrival Time	Green Light	Arrival Time	Green Light					
1	0433	0445	0519	0535	NO		2	M/c R2	
2	0600	0612	0646	0703	NO	P	3	R3	
3	0738	0755	0827	0835	Yes	F 10.5, 26	1	w/shop checking Comp K R1	
4	0910		0949	1004	NO		2		
5	1040		1118	1128	N		3		
6	1203		1239	1251	N		1		
7	1326		1450	1450	Y		2	Comp Car K change Parts	
8	1525						3		
9							1		
10							2		
11							3		
12									

Time of Fault/Delay	Fault/Delay Description	Notification Raised	Notification No.
0800	Swap Comp P not running Comp K running		
1345	Comp Car K change Parts		

A Continuity Test must be done before moving the Train after Rake changeover!

Document reviewed and necessary Notifications/Maintenance Orders raised. Crewleader Signature.....