Date 18.09.26 Loco No. R1005 Cab No 1 Facing Andoom Shift Driver/s JED Pete Day (Night) Shift

The following checks are to be performed at shift handover or close as practical

Vigilance Operational	Engine Oil	Radiator Water		End of Rake Marker Operational	Rake Leakage Check kPa
(Yes) No	(OK) Not OK Topped up	(OK) Not Ok Topped Up		Rake 1 (Y) N Rake 2 (Y) N Rake 3 (Y) N	Rake 1 Rake 2 Rake 3
Loco Comp Oil	(OK) Not OK Topped Up	Lead Rake1 2nd	Lead Rake2 2nd	Lead Rake3 2nd	Locomotive

			Comp Car	Comp Car	Comp Car	Comp Car	Comp Car	Comp Car	
Record time comp car/loco hrs taken									Radiator Water added(mm s/glass)
Rake 1		Engine Oil	Amt Added	Amt Added	Amt Added	Amt Added	Amt Added	Amt Added	Amt Added
Rake 2		Comp Oil	Amt Added	Amt Added	Amt Added	Amt Added	Amt Added	Amt Added	Amt Added
Rake 3		Comp Hrs							Loco Hrs
		Next Service							Cab Cleaned COVID
Locomotive	1540		Running in Auto / Manual Not Running	Running in Auto / Manual Not Running	Running In Auto / Manual Not Running	Running In Auto / Manual Not Running	Running In Auto / Manual Not Running	Running In Auto / Manual Not Running	Loco Km's Travelled
Fuel added to comp cars / Loco			Ltr's	Ltr's	Ltr's	Ltr's	Ltr's	Ltr's	800 Ltrs

Trip No	Dump Station Arrival Time	Dump Station Green Light	Load Station Arrival Time	Load Station Green Light	Delay to Production Yes / No	Delay Time minutes	Rake No	Reason for Delay	Manual Brake Pipe Continuity Completed (Train Drivers Initials Required)
1	1500			1605	Yes		3	one Drive on.	
2	1640		1710	1820	NO		1		JH
3	2055		2125	2223	NO		2		JH
4	2258		2336	2349	NO		3		JH
5	0014		0108	0112	NO		1		
6	0147		0233	0235	NO		2		
7	0310		0347	0355	NO		3	Loco FUEL 800 L	
8	0430						1		
9							2		
10							3		
11									
12									

Time of Fault/Delay	Fault/Delay Description	Notification Raised	Notification No.

A Continuity Test must be done before moving the Train after Rake changeover!

Document reviewed and necessary Notifications/Maintenance Orders raised. Crewleader Signature.....