Date 15/7/26 Loco No. A1005 Cab No 1 Facing Andoom Shift Driver/s Pete/Ted/Steve Day Night Shift

The following checks are to be performed at shift handover or close as practical

Vigilance Operational	Engine Oil	Radiator Water		End of Rake Marker Operational	Rake Leakage Check kPa
Yes No	Ok Not OK Topped up	OK Not Ok Topped Up		Rake 1 Y N Rake 2 Y N Rake 3 Y N	Rake 1 0 Rake 2 0 Rake 3 0
Loco Comp Oil	OK Not OK Topped Up	Lead Rake1 2nd	Lead Rake2 2nd	Lead Rake3 2nd	Locomotive

	Record time comp car/loco hrs taken		Comp Car	Comp Car	Comp Car	Comp Car	Comp Car	Comp Car	Radiator Water added(mm s/glass)
Rake 1		Engine Oil	Amt Added	Amt Added	Amt Added	Amt Added	Amt Added	Amt Added	Amt Added
Rake 2		Comp Oil	Amt Added	Amt Added	Amt Added	Amt Added	Amt Added	Amt Added	Amt Added
Rake 3		Comp Hrs							Loco Hrs 25222
		Next Service							Cab Cleaned COVID
Locomotive	1607		Running in Auto / Manual Not Running	Running in Auto / Manual Not Running	Running in Auto / Manual Not Running	Running in Auto / Manual Not Running	Running in Auto / Manual Not Running	Running in Auto / Manual Not Running	Loco Km's Travelled 509174
Fuel added to comp cars / Loco			Ltr's	Ltr's	Ltr's	Ltr's	Ltr's	Ltr's	Ltrs

Trip No	Dump Station Arrival Time	Dump Station Green Light	Load Station Arrival Time	Load Station Green Light	Delay to Production Yes / No	Delay Time minutes	Rake No	Reason for Delay	Manual Brake Pipe Continuity Completed (Train Drivers Initials Required)
1	1529		1606	1621	N		1	m/c	PH SGW
2	1651		1728	1742	N		2	m/c	PH SGW
3	1817		1850	1902	N		3	m/c	PH SGW
4	1937		2009	2021	N		1		
5	2056		2128	2140	N		2		
6	2215		2248	2256	N		3		
7	2331		0001	0013	N		1		
8	0048		"	0138	N		2		
9	0208		0250	0256	N		3		
10	0331						1		
11									
12									

Time of Fault/Delay	Fault/Delay Description	Notification Raised	Notification No.

A Continuity Test must be done before moving the Train after Rake changeover!

Document reviewed and necessary Notifications/Maintenance Orders raised. Crewleader Signature.....