Date 16 / 1 / 26 Loco No. R1005 Cab No 2 Facing Andoom Shift Driver/s Day / Night Shift

The following checks are to be performed at shift handover or close as practical

Vigilance Operational	Engine Oil	Radiator Water	End of Rake Marker Operational	Rake Leakage Check kPa
Yes / No	OK / Not OK / Topped up ¼50	OK / Not Ok / Topped Up	Rake 1 Y N Rake 2 Y N Rake 3 Y N	Rake 1 / Rake 2 / Rake 3
Loco Comp Oil: OK / Not OK / Topped Up				

Record time comp car/loco hrs taken			Lead	Rake1	2nd	Lead	Rake2	2nd	Lead	Rake3	2nd	Locomotive
Rake 1	0931	Engine Oil	Comp Car N	Comp Car J		Comp Car P	Comp Car O		Comp Car P	Comp Car M		Radiator Water added(mm s/glass)
Rake 2	6513	Comp Oil	Amt Added	Amt Added		Amt Added	Amt Added		Amt Added	Amt Added		Amt Added
Rake 3	0240	Comp Hrs	34871	15403		15214	32750		7124	17152		Amt Added
		Next Service	35000	15500		16000	33500		7001	18137		Loco Hrs
Locomotive			Running in Auto / Manual / Not Running	Running in Auto / Manual / Not Running		Running in Auto / Manual / Not Running	Running in Auto / Manual / Not Running		Running in Auto / Manual / Not Running	Running in Auto / Manual / Not Running		Cab Cleaned COVID
Fuel added to comp cars / Loco			Ltr's	Ltr's		Ltr's	Ltr's		Ltr's	Ltr's		Loco Km's Travelled
												1100 Ltrs

Trip No	Dump Station		Load Station		Delay to Production Yes / No	Delay Time minutes	Rake No	Reason for Delay	Manual Brake Pipe Continuity Completed (Train Drivers Initials Required)
	Arrival Time	Green Light	Arrival Time	Green Light					
1	0230		0410	0441			1		RGH
2	0516		0550	0608			2		RGH
3	0743		0847	0855			3		RGH
4	0930		1003	1050			1		
5	1125		1202	1315			2	Loco Fuel 1100L	
6	1350		1430	1457			3		
7	1532						1		
8							2		
9							3		
10									
11									
12									

Time of Fault/Delay	Fault/Delay Description	Notification Raised	Notification No.

A Continuity Test must be done before moving the Train after Rake changeover!

Document reviewed and necessary Notifications/Maintenance Orders raised. Crewleader Signature.....