Date 16/2/26 Loco No. R1005 Cab No 1 Facing Andoom Shift Driver/s Pete Ted Steve (Day) Night Shift

The following checks are to be performed at shift handover or close as practical

Vigilance Operational	Engine Oil	Radiator Water		End of Rake Marker Operational	Rake Leakage Check kPa
(Yes) No	(Ok) Not OK Topped up	(OK) Not Ok Topped Up		Rake 1 (Y) N Rake 2 (Y) N Rake 3 (Y) N	Rake 1 0 Rake 2 Rake 3 0
Loco Comp Oil	(OK) Not OK Topped Up				

Record time comp car/loco hrs taken			Lead	Rake1	2nd	Lead	Rake2	2nd	Lead	Rake3	2nd	Locomotive
Rake 1		Engine Oil	Comp Car	Comp Car		Comp Car P	Comp Car O		Comp Car I	Comp Car M		Radiator Water added(mm s/glass)
Rake 2	0432	Comp Oil	Amt Added	Amt Added		Amt Added	Amt Added		Amt Added	Amt Added		Amt Added
Rake 3	0630	Comp Hrs				15661	32800		10193	17419		Loco Hrs 22903
		Next Service				16000	33500		11000	18137		Cab Cleaned COVID
Locomotive	0418		Running in Auto / Manual Not Running	Running in Auto / Manual Not Running		Running in Auto / ~~Manual~~ Not Running	~~Running in Auto / Manual~~ Not Running		Running in Auto / ~~Manual~~ Not Running	~~Running in Auto / Manual~~ Not Running		Loco Km's Travelled 468419
Fuel added to comp cars / Loco			Ltr's	Ltr's		Ltr's	Ltr's		Ltr's	Ltr's		Ltrs

Trip No	Dump Station Arrival Time	Dump Station Green Light	Load Station Arrival Time	Load Station Green Light	Delay to Production Yes / No	Delay Time minutes	Rake No	Reason for Delay	Manual Brake Pipe Continuity Completed (Train Drivers Initials Required)
1	0330		0414	0515	N		~~1~~		
2	0550		0625	0714	N		3		
3	0750			1111	Yes		1	m/c	RH
4	1146	1420	1455	1540	Yes		2	m/c	RL
5	1615						3		
6							1		
7							2		
8							3		
9									
10									
11									
12									

Time of Fault/Delay	Fault/Delay Description	Notification Raised	Notification No.

A Continuity Test must be done before moving the Train after Rake changeover!

Document reviewed and necessary Notifications/Maintenance Orders raised. Crewleader Signature.....