Date 16/2/26 Loco No. R1005 Cab No 1 Facing Andoom Shift Driver/s Adam Trudi Day (Night) Shift

The following checks are to be performed at shift handover or close as practical

Vigilance Operational	Engine Oil 2 90G	Radiator Water	End of Rake Marker Operational	Rake Leakage Check kPa
(Yes) No	(Ok) Not OK Topped up	(OK) Not Ok Topped Up	Rake 1 Y N Rake 2 (Y) N Rake 3 (Y) N	Rake 1 0 Rake 2 1 Rake 3 0

Loco Comp Oil	Lead	Rake1	2nd	Lead	Rake2	2nd	Lead	Rake3	2nd	Locomotive
(OK) Not OK Topped Up	Comp Car	Comp Car		Comp Car	Comp Car		Comp Car	Comp Car		Radiator Water added(mm s/glass)

Record time comp car/loco hrs taken												
Rake 1		Engine Oil	Amt Added	Amt Added	Amt Added	Amt Added	Amt Added	Amt Added	Amt Added
Rake 2		Comp Oil	Amt Added	Amt Added	Amt Added	Amt Added	Amt Added	Amt Added	Amt Added
Rake 3		Comp Hrs							Loco Hrs 22916
		Next Service							Cab Cleaned COVID
Locomotive	1713		Running in Auto / Manual Not Running	Running in Auto / Manual Not Running	Running in Auto / Manual Not Running	Running in Auto / Manual Not Running	Running in Auto / Manual Not Running	Running in Auto / Manual Not Running	Loco Km's Travelled 468576
Fuel added to comp cars / Loco			Ltr's	Ltr's	Ltr's	Ltr's	Ltr's	Ltr's	1900 Ltrs

Trip No	Dump Station		Load Station		Delay to Production Yes / No	Delay Time minutes	Rake No	Reason for Delay	Manual Brake Pipe Continuity Completed (Train Drivers Initials Required)
	Arrival Time	Green Light	Arrival Time	Green Light					
1	1615		1655	1809	N		3		
2	1844		1920	2049	N		1		
3	2123		2207	2318	N		2		
4	2352		0030	0140	N		3		
5	0215		0310	0402	N		1	FUEL 1900L	
6	0437						2		
7									
8									
9									
10									
11									
12									

Time of Fault/Delay	Fault/Delay Description	Notification Raised	Notification No.
	Dynamic - No load		

A Continuity Test must be done before moving the Train after Rake changeover!

Document reviewed and necessary Notifications/Maintenance Orders raised. Crewleader Signature.....