Date 16/3/26 Loco No. R1005 Cab No 2 Facing Andoom Shift Driver/s Ted Steele Pete (Day) Night Shift

The following checks are to be performed at shift handover or close as practical

Vigilance Operational	Engine Oil	Radiator Water	End of Rake Marker Operational	Rake Leakage Check kPa
(Yes) No	(Ok) Not OK Topped up	(OK) Not Ok Topped Up	Rake 1 (Y) N Rake 2 (Y) N Rake 3 (Y) N	Rake 1 0 Rake 2 0 Rake 3 0
Loco Comp Oil: (OK) Not OK Topped Up				

Record time comp car/loco hrs taken			Lead Rake1 2nd		Lead Rake2 2nd		Lead Rake3 2nd		Locomotive
Rake 1	0701	Engine Oil	Comp Car J Amt Added	Comp Car K Amt Added	Comp Car P Amt Added	Comp Car N Amt Added	Comp Car I Amt Added	Comp Car M Amt Added	Radiator Water added(mm s/glass) Amt Added
Rake 2	1148	Comp Oil	Amt Added	Amt Added	Amt Added	Amt Added	Amt Added	Amt Added	Amt Added
Rake 3	0649	Comp Hrs	15707	7599	15994	35174	10415	7648	Loco Hrs 23463
		Next Service	16500	8100	16000	36000	11000	18137	Cab Cleaned COVID
Locomotive	0754		(Running in Auto) / Manual Not Running	Running in Auto / Manual (Not Running)	Running in Auto / ~~Manual~~ ~~Not Running~~	~~Running in Auto / Manual~~ Not Running	Running in Auto / Manual (Not Running)	Running in Auto / Manual Not Running	Loco Km's Travelled 477911
Fuel added to comp cars / Loco			Ltr's	Ltr's	Ltr's	Ltr's	Ltr's	Ltr's	702 Ltrs

Trip No	Dump Station Arrival Time	Dump Station Green Light	Load Station Arrival Time	Load Station Green Light	Delay to Production Yes / No	Delay Time minutes	Rake No	Reason for Delay	Manual Brake Pipe Continuity Completed (Train Drivers Initials Required)
1	0450		0530	0613	No		2		PH
2	0648		0717	0947	No		3		PH
3	1022						1		PH
4							2		
5							3	LOCO FUEL 702L	
6									
7									
8									
9									
10									
11									
12									

Time of Fault/Delay	Fault/Delay Description	Notification Raised	Notification No.

A Continuity Test must be done before moving the Train after Rake changeover!

Document reviewed and necessary Notifications/Maintenance Orders raised. Crewleader Signature.....